



MX-Sensor_V6.26 Function List For AU Market (Note:For reference only)

NOTES:

● This function is supported. ○ This function is not supported. Mark explaining(Red:New, Yellow: Modify)

Special Declaration:

1). If the "Relearn Type" of MX-Sensor is only OBD type, and the "OBD-II Function" has not been released for the moment, you can just do the clone for relearning the MX-Sensor.

2). All the Automatic Relearn Procedure for MX-Sensor, the drive speed should be controlled between 16 mph (25 km/h) and 64 mph (100 km/h).

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufactuer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Abarth	124 Spider	2016/10-2022/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Abarth	124 Spider	2016/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Abarth	500	2008/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Abarth	500	2008/01-2022/12	433MHz		●	●	●	O/A	433MHz	Schrader	●	●
Abarth	500C	2010/01-2019/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Abarth	595	2014/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Abarth	595 C	2015/01-2021/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Abarth	599	2014/03-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Abarth	695 Rivale	2019/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Acura	NSX	2016/06-2020/12	315MHz		●	●	○	O	315MHz	Continental	●	●
Alfa Romeo	4C	2013/01-2021/12	433MHz	960/961	●	●	●	O/A	433MHz	Schrader	●	●
Alfa Romeo	8C	2007/01-2009/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Alfa Romeo	Giulia	2016/01-2021/12	50547691 433MHz	952	●	●	●	O/A	433MHz	Continental	●	●
Alfa Romeo	Giulietta	2010/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Alfa Romeo	Giulietta	2014/01-2022/12	433MHz	940	○	●	○	A	433MHz	Schrader	●	●
Alfa Romeo	Giulietta	2010/01-2013/12	433MHz		○	●	○	C	433MHz	TRW	●	●
Alfa Romeo	MiTo	2013/08-2020/12	433MHz	955	●	●	○	O/A	433MHz	Schrader	●	●
Alfa Romeo	MiTo	2008/01-2013/07	433MHz	955	●	●	○	O	433MHz	TRW	●	●
Alfa Romeo	Quadrifoglio	2018/01-2021/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Alfa Romeo	Quadrifoglio	2016/01-2017/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
Alfa Romeo	Spider	2006/06-2017/12	433MHz	946	○	●	○	C	433MHz	TRW	●	●
Alfa Romeo	Stelvio	2017/01-2022/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Alpina	Alpina 3	2018/10-2021/06	433MHz	G20	●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	Alpina 3	2013/01-2019/12	433MHz	F30/F32	●	●	○	A	433MHz	Continental	●	●
Alpina	Alpina 3	1998/05-2008/01	433MHz	E46	●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	Alpina 3	2007/09-2014/03	433MHz	E90	●	●	○	A	433MHz	Huf/Beru	●	●
Alpina	Alpina 4	2013/07-2020/08	433MHz	F30/F32	●	●	○	A	433MHz	Continental	●	●
Alpina	Alpina 5	2017/01-2022/12	433MHz	G30	●	●	○	A	433MHz	Schrader	●	●
Alpina	Alpina 7	2015/01-2022/12	433MHz	G11	●	●	○	A	433MHz	Schrader	●	●
Alpina	Alpina XB7	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Alpina	XD3	2018/01-2022/06	433MHz	G01	●	●	○	A	433MHz	Schrader	●	●
Aston Martin	Cygnnet	2011/01-2018/06	433MHz		●	●	○	A	433MHz	Pacific	●	●
Aston Martin	DB11	2016/01-2022/12	433MHz	VH500	○	●	○	A	433MHz	Schrader	●	●
Aston Martin	DB9	2009/01-2018/12	433MHz	AM803	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	DBS	2007/01-2015/12	433MHz	V12	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	DBS Superleggera	2018/01-2022/12	433MHz	VH500	○	●	○	A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Aston Martin	DBX	2020/04-2022/12	HUF 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Aston Martin	Lagonda	2015/01-2019/12	433MHz	COMET	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Rapide	2010/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Rapide S	2010/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Valkyrie	2018/01-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vanquish	2012/01-2020/12	433MHz	AM310	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Vantage	2005/07-2022/12	433MHz	AM305	●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Virage	2010/01-2020/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Aston Martin	Zagato	2011/01-2012/08	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	A1	2010/06-2019/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	A3	2003/01-2012/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Audi	A3	2010/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A3	2012/06-2022/12	433MHz	8L	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A4	2007/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A4	2007/01-2012/12	315MHz Continental		●	●	○	A	315MHz	Continental	●	●
Audi	A4	2012/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Audi	A4	2001/01-2011/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	A4 Allroad	2008/01-2012/12	315MHz		●	●	○	C	315MHz	Continental	●	●
Audi	A5	2006/09-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A5	2007/01-2012/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Audi	A5	2006/12-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A6	2000/01-2005/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	A6	2018/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A6	2010/01-2017/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Audi	A6	2014/03-2019/12	433MHz 7PP907275F		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A6	2011/01-2022/12	433MHz	4G	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A6 Allroad	2009/11-2019/12	433MHz	4G	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	A7	2010/09-2022/12	433MHz 5Q0907275	4G	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A7	2012/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A8	2009/11-2017/10	433MHz	4H/4L	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A8	2010/01-2022/12	433MHz 5Q0907275		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	A8	2009/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	A8	2002/10-2012/12	433MHz	4E	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	A9	2019/01-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	Q2	2016/01-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	Q2	2015/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q3	2011/06-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q3	2011/07-2022/12	433MHz	8U	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	Q4	2019/09-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	Q5	2008/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q5	2008/01-2015/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Audi	Q5	2008/09-2022/12	433MHz	8R	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	Q6	2018/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Audi	Q7	2005/09-2015/12	433MHz	4L/AU716	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	Q7	2015/01-2022/12	MLB 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	Q7	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q8	2018/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	Q8	2018/01-2022/12	433MHz	4M	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	R8	2009/06-2022/12	433MHz 7PP907275F	AU714	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	R8	2014/03-2021/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	R8	2015/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS Q3	2018/01-2021/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Audi	RS3	2016/07-2022/12	433MHz	8V	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS3	2013/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS4	2006/04-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS4	2006/04-2018/12	433MHz	8E/B7	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS4	2008/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS5	2012/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS5	2010/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS5	2007/01-2012/12	315MHz		○	●	○	C	315MHz	Continental	●	●
Audi	RS6	2019/01-2022/12	5Q0907275 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Audi	RS6	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS6	2008/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS6	2000/01-2007/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS6/RS6 Plus	2013/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RS7	2018/03-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	RS7	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	RS7	2010/01-2021/06	433MHz 7PP907275F		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	RSQ8	2019/12-2022/06	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Audi	S3	2003/01-2012/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Audi	S4	2009/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	S4	2007/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S5	2012/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Audi	S5	2007/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S6	2000/01-2005/12	4D0907275 433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	S6	2004/01-2009/12	7PP907275F 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	S7	2012/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	S8	2009/11-2017/10	433MHz	D4	●	●	○	A	433MHz	Huf/Beru	●	●
Audi	SQ5	2012/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	SQ5	2014/01-2021/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	SQ7	2016/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	SQ7	2016/01-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Audi	SQ8	2020/01-2021/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Audi	TT	2014/02-2022/12	433MHz	AU334	●	●	○	O/A	433MHz	Huf/Beru	●	●
Audi	TT	2007/01-2014/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Audi	TT	2006/04-2014/02	Indirect		○	○	○	A	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Audi	TT	2014/03-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	TTS	2012/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Audi	TTS	2016/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Audi	e-tron	2018/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	1 Series	2008/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	1 Series	2010/07-2022/12	433MHz	F20/F21/F52	●	●	○	A	433MHz	Continental	●	●
BMW	1 Series	2019/07-2022/12	433MHz	F40	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	2 Series	2019/11-2022/12	433MHz	F44/G42	●	●	○	C	433MHz	Huf/Beru	●	●
BMW	2 Series	2014/01-2022/12	433MHz	F22/F23/F45/F46	●	●	○	A	433MHz	Continental	●	●
BMW	3 Series	1999/03-2011/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	3 Series	2014/01-2019/12	433MHz	F30/F31/F35	●	●	○	A	433MHz	Continental	●	●
BMW	3 Series	2012/01-2013/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	1998/01-2007/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	2017/10-2022/12	433MHz	G20	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	3 Series	2007/01-2013/12	433MHz	E9x	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	3 Series GT	2013/01-2021/06	433MHz	F34	●	●	○	A	433MHz	Continental	●	●
BMW	4 Series	2020/09-2022/12	433MHz	G22/G23/G26	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	4 Series	2013/07-2020/12	433MHz	F32/F33/F36	●	●	○	A	433MHz	Continental	●	●
BMW	5 Series	2010/09-2014/02	433MHz	F10/F11/F07/F18	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series	2014/03-2017/12	433MHz	F07/F10/F11	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	5 Series	2007/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	5 Series	2003/05-2010/11	433MHz	E60/E61/F07	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	2001/01-2009/12	433MHz	E65	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	5 Series	2017/01-2022/12	433MHz	G30/G31/G38	●	●	○	A	433MHz	Schrader	●	●
BMW	5 Series	1999/01-2004/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	5 Series GT	2017/01-2019/12	433MHz	G32	●	●	○	A	433MHz	Schrader	●	●
BMW	5 Series GT	2014/04-2018/06	433MHz	F07 LCI	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series	2014/03-2022/12	433MHz	F12/F13/F06	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series	2011/01-2014/03	433MHz	F06/F12/F13	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	6 Series	2003/01-2007/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	6 Series	2003/01-2011/12	433MHz	E63/E64	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	6 Series GT	2016/09-2022/12	433MHz	G14/G32	●	●	○	A	433MHz	Schrader	●	●
BMW	7 Series	2014/10-2022/12	433MHz	G11/G12	●	●	○	A	433MHz	Schrader	●	●
BMW	7 Series	2014/03-2015/05	433MHz	F01/F02	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	7 Series	1999/01-2001/12	Indirect	E38	○	○	○	A	N/A	N/A	Indirect	●
BMW	7 Series	2010/10-2015/12	433MHz	F01/F02/F04	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	7 Series	2001/01-2008/12	433MHz	E66	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	8 Series	2018/07-2022/12	433MHz	G14/G15/G16/F91/F92/F93	●	●	○	C	433MHz	Schrader	●	●
BMW	M2	2014/11-2021/12	433MHz	F87	●	●	○	A	433MHz	Continental	●	●
BMW	M3	1999/01-2006/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	M3	2006/01-2007/12	433MHz (36106790054)		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	M3	2008/01-2013/12	433MHz (36106856227)		●	●	○	O/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	M3	2007/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	M3	2014/01-2019/12	433MHz	F80	●	●	○	A	433MHz	Continental	●	●
BMW	M3	2012/01-2013/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	M4	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	M4	2014/01-2020/12	433MHz	F82/F83	●	●	○	A	433MHz	Continental	●	●
BMW	M5	2010/09-2014/03	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M5	2005/01-2010/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	M5	1999/01-2003/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	M5	2014/04-2018/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M5	2016/01-2022/12	36106872774 433MHz	F90	●	●	○	A	433MHz	Schrader	●	●
BMW	M6	2014/03-2018/12	433MHz	F12	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M6	2014/01-2018/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M6	2005/01-2011/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	M6	2011/06-2015/12	36106856227 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	M8	2019/01-2022/12	433MHz		●	●	○	C	433MHz	Schrader	●	●
BMW	Motorcycle	2010/01-2019/12	433MHz		○	○	○		433MHz	Schrader	Activate Only	●
BMW	X1	2014/03-2016/06	433MHz	E84	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X1	2015/08-2022/12	433MHz	F48	●	●	○	A	433MHz	Continental	●	●
BMW	X1	2008/09-2015/12	OYGTSSRE4D 433MHz	E84	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X2	2016/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
BMW	X3	2017/01-2022/12	433MHz	G01/G08/F97	●	●	○	A	433MHz	Schrader	●	●
BMW	X3	2010/01-2017/12	36106798872 433MHz	F25	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X3	2010/11-2014/03	433MHz	F25	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X3	2003/01-2010/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X4	2017/03-2022/12	433MHz	G02/F98	●	●	○	A	433MHz	Schrader	●	●
BMW	X4	2014/01-2019/12	433MHz	F26	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X5	2017/09-2022/12	433MHz	F95/G05/G18	●	●	○	A	433MHz	Schrader	●	●
BMW	X5	2013/05-2019/12	433MHz	F15/F85	●	●	○	A	433MHz	Continental	●	●
BMW	X5	2010/10-2013/06	433MHz	E70	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X5	2000/01-2005/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
BMW	X5	2004/01-2010/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X6	2018/07-2022/12	433MHz	F96/G06	●	●	○	C	433MHz	Schrader	●	●
BMW	X6	2014/08-2019/12	433MHz	F16/F86	●	●	○	A	433MHz	Continental	●	●
BMW	X6	2008/01-2014/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	X6	2011/12-2014/07	433MHz	E71	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	X7	2018/01-2022/12	433MHz	G07	●	●	○	A	433MHz	Schrader	●	●
BMW	Z4	2009/02-2019/02	433MHz	E89	●	●	○	O/A	433MHz	Huf/Beru	●	●
BMW	Z4	2003/01-2008/12	Indirect	E38	○	○	○	A	N/A	N/A	Indirect	●
BMW	Z4	2019/03-2020/06	433MHz	G02	●	●	○	A	433MHz	Schrader	●	●
BMW	Z4	2018/11-2022/12	433MHz	G29	●	●	○	A	433MHz	Huf/Beru	●	●
BMW	Z4	2009/01-2013/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
BMW	i3	2013/01-2022/06	433MHz	I01/I12	●	●	○	A	433MHz	Continental	●	●
BMW	i4	2021/01-2022/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
BMW	i5	2019/01-2019/12	433MHz	I05	●	●	○	A	433MHz	Continental	●	●
BMW	i8	2013/01-2020/12	433MHz	I01/I12	●	●	○	A	433MHz	Continental	●	●
BMW	ix	2020/11-2022/12	433MHz		●	●	○	C	433MHz	Schrader	●	●
BMW	ix1	2022/06-2022/12	433MHz	F48	●	●	○	C	433MHz	Huf/Beru	●	●
BMW	ix3	2020/11-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Bentley	Arnage	2008/01-2011/09	7PP907275F 433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Bentley	Bentayga	2016/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Bentley	Bentayga	2016/01-2022/12	433MHz 5Q0907275		●	●	○	O/A	433MHz	Huf/Beru	●	●
Bentley	Brooklands	2008/01-2011/12	433MHz		●	●	○	C	433MHz	Huf/Beru	●	●
Bentley	Continental Flying Spur	2005/03-2020/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Bentley	Continental GT	2005/06-2021/12	433MHz BY634		●	●	○	A	433MHz	Huf/Beru	●	●
Bentley	Continental GT	2003/09-2005/05	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Bentley	Flying Spur	2019/01-2022/12	5Q0907275 433MHz		●	●	○	O	433MHz	Huf/Beru	●	●
Bentley	Flying Spur	2011/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Bentley	Mulliner	2021/01-2022/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Bentley	Mulsanne	2001/01-2020/12	7PP907275F 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Bentley	Mulsanne	2017/01-2021/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Cadillac	CT6	2019/01-2022/12	433MHz 13516165		●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	CTS	2013/01-2013/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2012/01-2012/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2010/01-2011/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2007/10-2008/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2007/01-2007/09	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2016/01-2021/12	315MHz 13598772		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2009/01-2009/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2016/01-2019/12	433MHz 13598787		●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	CTS	2016/01-2019/12	315MHz 13598786		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2014/01-2015/12	315MHz 20964159		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2014/01-2015/12	315MHz 13581558		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	CTS	2014/01-2014/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	DTS	2009/01-2013/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	DTS	2008/01-2008/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	DTS	2007/01-2007/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	DTS	2006/01-2006/12	315MHz 25920615		○	●	○	S	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Cadillac	DTS	2005/01-2006/12	315MHz 15268606		○	●	○	S	315MHz	Schrader	●	●
Cadillac	Deville	2004/01-2004/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Cadillac	Deville	2000/01-2003/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Cadillac	Deville	2005/01-2007/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Cadillac	Escalade	2008/01-2008/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2007/01-2007/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2007/01-2007/12	Clamp in 315MHz		●	●	●	O/S	315MHz	TRW	●	●
Cadillac	Escalade	2009/01-2011/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2012/01-2012/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2013/01-2013/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2014/01-2014/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2018/01-2019/12	433MHz 13516165		●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	Escalade	2017/01-2020/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Escalade	2015/01-2016/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
Cadillac	SRX	2015/01-2016/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	SRX	2004/01-2006/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Cadillac	SRX	2007/01-2008/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	SRX	2009/01-2009/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	SRX	2010/01-2012/12	433MHz	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	SRX	2013/01-2013/12	433MHz	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	SRX	2014/01-2016/12	433MHz	GMT166	●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	STS	2004/01-2007/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Cadillac	STS	2008/01-2008/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Cadillac	STS	2009/01-2011/12	Clamp in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	STS	2009/01-2011/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Cadillac	Seville	2001/01-2003/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Cadillac	Seville	2004/01-2006/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Cadillac	XLR	2006/01-2009/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Cadillac	XLR	2004/01-2005/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Cadillac	XLR-V	2016/01-2019/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Cadillac	XT3	2018/01-2019/12	315MHz	D2UL	○	●	○	S	315MHz	Schrader	●	●
Cadillac	XT4	2018/11-2022/12	433MHz	E2UL	●	●	○	O/S	433MHz	Schrader	●	●
Cadillac	XT4	2018/01-2019/12	315MHz	E2UL	●	●	○	O/S	315MHz	Schrader	●	●
Cadillac	XT6	2019/01-2022/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Camaro	2012/01-2012/12	315MHz 12768826		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Camaro	2018/01-2019/12	315MHz 13598786		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Camaro	2017/01-2022/12	Clamp in 433MHz (13598787)		●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Camaro	2017/01-2020/12	Snap in 433MHz		●	●	●	O/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Camaro	2016/01-2016/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Camaro	2016/01-2016/12	Clamp in 433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Camaro	2016/01-2016/12	Snap in 433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Camaro	2014/01-2015/12	315MHz 22854866		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Camaro	2013/01-2013/12	315MHz 12768826		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Caprice	2011/01-2013/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Colorado	2017/01-2019/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Corvette	2005/01-2009/12	315MHz 25758220	C6	●	●	○	O/S	315MHz	Schrader	●	●
Chevrolet	Corvette	1997/01-2000/12	315MHz	C5	○	●	○	S	315MHz	Schrader	●	●
Chevrolet	Corvette	2001/01-2002/12	315MHz	C5	●	●	○	S	315MHz	Schrader	●	●
Chevrolet	Corvette	2003/01-2004/12	315MHz	C5	●	●	○	S	315MHz	Schrader	●	●
Chevrolet	Corvette	2009/01-2009/12	315MHz 13598771	C6	●	●	○	O/S	315MHz	Schrader	●	●
Chevrolet	Corvette	2010/01-2011/12	315MHz	C6	●	●	○	O/S	315MHz	Schrader	●	●
Chevrolet	Corvette	2010/01-2014/12	433MHz	C6	●	●	○	O/S	433MHz	Schrader	●	●
Chevrolet	Corvette	2012/01-2012/12	315MHz	C6	●	●	○	O/S	315MHz	Schrader	●	●
Chevrolet	Corvette	2013/01-2013/12	315MHz	C6	●	●	○	O/S	315MHz	Schrader	●	●
Chevrolet	Corvette	2014/01-2019/12	C7 433MHz	Y1BC	●	●	●	O/A	433MHz	Schrader	●	●
Chevrolet	Cruze	2013/01-2015/12	433MHz	DISC/ D1JC/ D1WC/ KL1J	●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Cruze	2008/10-2010/12	433MHz	DISC/ D1JC/ D1WC/ KL1J	○	●	○	S	433MHz	Schrader	●	●
Chevrolet	Cruze	2011/01-2011/12	433MHz	DISC/ D1JC/ D1WC/ KL1J	●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Cruze	2012/01-2012/12	433MHz	DISC/ D1JC/ D1WC/ KL1J	●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Malibu	2013/01-2015/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Silverado	2009/01-2011/12	Clamp in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Silverado	2013/10-2014/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Silverado	2009/01-2013/09	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Silverado	2015/01-2016/10	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Silverado	2015/01-2016/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Silverado	2015/01-2020/12	433MHz	K2XC	●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Silverado	2016/11-2019/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Chevrolet	Silverado	2010/07-2014/12	433MHz	K2XC	●	●	●	O/S	433MHz	Schrader	●	●
Chevrolet	Spark	2015/01-2015/12	433MHz	M1JC	●	●	●	O/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Chevrolet	Spark	2013/01-2014/12	433MHz	M1JC	●	●	●	0/S	433MHz	Schrader	●	●
Chevrolet	Uplander	2004/01-2010/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Chrysler	200	2018/01-2020/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Chrysler	200	2017/01-2017/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Chrysler	200	2014/01-2016/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Chrysler	300	2011/01-2013/12	433MHz	LX	●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300 SRT	2018/01-2021/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Chrysler	300 SRT	2013/01-2017/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300 SRT	2010/01-2012/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300C	2018/01-2021/06	18 inch 433MHz		●	●	○	A	433MHz	Schrader	●	●
Chrysler	300C	2005/06-2009/05	433MHz	LE48	●	●	●	0/A	433MHz	Continental	●	●
Chrysler	300C	2009/06-2017/12	18 inch 433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300C	2014/01-2015/12	433MHz 56029400AE		●	●	●	0/A	433MHz	Schrader	●	●
Chrysler	300C	2018/01-2019/12	433MHz 56029400AD		●	●	○	C	433MHz	Schrader	●	●
Chrysler	300C	2014/01-2017/12	433MHz 56029400AD		●	●	●	0	433MHz	Schrader	●	●
Chrysler	Crossfire	2003/10-2009/01	433MHz		●	●	○	C	433MHz	Schrader	●	●
Chrysler	Grand Voyager	2007/01-2010/12	433MHz	RT	●	●	●	0	433MHz	Schrader	●	●
Chrysler	Grand Voyager	2018/01-2020/03	433MHz	RT	●	●	○	S	433MHz	Schrader	●	●
Chrysler	Grand Voyager	2011/01-2017/12	433MHz	RT	●	●	●	0/S	433MHz	Schrader	●	●
Chrysler	Grand Voyager	2016/01-2017/12	433MHz	RU	●	●	●	0/A	433MHz	Continental	●	●
Chrysler	Grand Voyager	2018/01-2019/12	433MHz	RU	●	●	○	A	433MHz	Continental	●	●
Chrysler	PT Cruiser	2008/01-2008/12	433MHz	LX	●	●	●	0/A	433MHz	Continental	●	●
Chrysler	Sebring	2006/01-2010/12	433MHz	JS	●	●	●	0/A	433MHz	Continental	●	●
Chrysler	Voyager	2018/01-2019/12	433MHz	RT	●	●	○	C	433MHz	Schrader	●	●
Chrysler	Voyager	2011/01-2017/12	433MHz	RT	●	●	●	0	433MHz	Schrader	●	●
Chrysler	Voyager	2002/01-2003/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
Chrysler	Ypsilon	2011/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Chrysler	Ypsilon	2018/01-2019/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Citroen	Berlingo	2008/01-2013/09	433MHz	B9	●	●	○	0	433MHz	Schrader	●	●
Citroen	Berlingo	2016/03-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	Berlingo	2013/10-2019/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Citroen	C3	2009/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Citroen	C4	2013/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	C4	2004/09-2010/07	433MHz	B5	●	●	○	0	433MHz	Continental	●	●
Citroen	C4	2004/01-2014/09	433MHz	B53/B7	●	●	○	0	433MHz	Schrader	●	●
Citroen	C4	2013/10-2019/12	433MHz	B58	●	●	○	0/A	433MHz	Schrader	●	●
Citroen	C4 Aircross	2012/01-2021/12	433MHz		●	●	○	0/S	433MHz	Continental	●	●
Citroen	C5	2000/12-2004/07	433MHz	X40	●	●	○	0	433MHz	Schrader	●	●
Citroen	C5	2004/08-2013/08	433MHz	X3/X40	●	●	○	0	433MHz	Continental	●	●
Citroen	C5	2008/01-2020/12	433MHz	X7	●	●	○	0/A	433MHz	Schrader	●	●
Citroen	C5 II (RC_)	2004/06-2013/12	433MHz	X3/X40	●	●	○	0	433MHz	Continental	●	●
Citroen	C6	2005/01-2013/12	433MHz	X6	●	●	○	0	433MHz	Continental	●	●
Citroen	C8	2005/10-2015/12	433MHz	V3	●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, 0=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Citroen	C8	2002/01-2005/09	433MHz	V3	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS3	2015/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Citroen	DS4	2010/01-2014/01	433MHz	B75	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS4	2014/02-2020/12	433MHz	B81	●	●	○	0/A	433MHz	Schrader	●	●
Citroen	DS5	2014/02-2019/12	433MHz	X2/50	●	●	○	0	433MHz	Schrader	●	●
Citroen	DS5	2011/01-2014/01	433MHz	B81	●	●	○	0	433MHz	Schrader	●	●
Dodge	Avenger	2007/01-2014/12	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Dodge	Avenger	2006/01-2013/12	433MHz	JS41D	●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Caliber	2008/01-2009/12	315MHz	PM	●	●	●	0/A	315MHz	Continental	●	●
Dodge	Caliber	2007/01-2007/12	315MHz	PM	●	●	●	0/A	315MHz	Continental	●	●
Dodge	Challenger	2014/01-2017/12	433MHz	LC22	●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Challenger	2018/01-2018/12	433MHz	LC22	●	●	○	A	433MHz	Schrader	●	●
Dodge	Challenger	2019/01-2022/12	433MHz	LC22	●	●	○	A	433MHz	Schrader	●	●
Dodge	Charger	2011/01-2013/12	433MHz	LX48D/LD	●	●	●	0	433MHz	Schrader	●	●
Dodge	Charger SRT	2015/01-2015/12	433MHz		●	●	●	0	433MHz	Schrader	●	●
Dodge	Dakota	2008/01-2010/12	Snap in 315MHz	ND	●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Dakota	2008/01-2010/12	Clamp in 315MHz	ND	●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Dakota	2007/01-2007/12	315MHz	ND	●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Dart	2012/10-2019/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Dodge	Durango	2011/01-2013/12	433MHz	WD	●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Grand Caravan	2014/01-2015/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Grand Caravan	2011/01-2013/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Grand Caravan	2008/01-2010/12	433MHz		●	●	●	0/A	433MHz	Continental	●	●
Dodge	Journey	2018/01-2019/12	433MHz	JC49	●	●	○	A	433MHz	Schrader	●	●
Dodge	Journey	2017/11-2017/12	433MHz	JC49	●	●	●	0	433MHz	Schrader	●	●
Dodge	Journey	2014/01-2017/10	433MHz	JC49	●	●	●	0	433MHz	Schrader	●	●
Dodge	Journey	2011/01-2013/12	433MHz	JC	●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Journey	2008/01-2010/12	433MHz	JC49	●	●	●	0/A	433MHz	Continental	●	●
Dodge	Magnum	2005/01-2008/12	315MHz		●	●	●	0/A	315MHz	Continental	●	●
Dodge	Nitro	2009/01-2012/12	315MHz	KA	●	●	●	0/A	315MHz	Schrader	●	●
Dodge	Ram 1500	2010/01-2013/09	433MHz	D2	●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Ram 1500	2019/01-2022/12	DT 433MHz		●	●	○	A	433MHz	Schrader	●	●
Dodge	Ram 3500	2010/01-2013/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Ram Series	2014/01-2017/12	433MHz	DS/DJ	●	●	●	0	433MHz	TRW	●	●
Dodge	Ram Series	2018/01-2021/12	433MHz	DS/DJ	●	●	○	C	433MHz	TRW	●	●
Dodge	SRT Viper	2010/01-2017/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Dodge	Viper	2003/01-2011/12	433MHz	ZB	○	●	○	C	433MHz	Schrader	●	●
Ferrari	458 Spider	2009/01-2020/12	433MHz	F142	●	●	○	0/A	433MHz	Huf/Beru	●	●
Ferrari	488	2015/01-2021/12	433MHz	F142	○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	575M Maranello	2002/01-2006/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Ferrari	599 GTB	2004/01-2014/12	433MHz	F141	●	●	○	0/A	433MHz	Huf/Beru	●	●
Ferrari	599 GTO	2004/01-2012/12	433MHz	F141	●	●	○	0/A	433MHz	Huf/Beru	●	●
Ferrari	612 Scaglietti	2004/01-2012/12	433MHz	F137	●	●	○	0/A	433MHz	Huf/Beru	●	●
Ferrari	812 Superfast	2016/01-2021/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Ferrari	CTC4 Lusso T	2017/01-2019/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ferrari	California	2008/10-2017/12	433MHz	F149	●	●	○	O/A	433MHz	Huf/Beru	●	●
Ferrari	Enzo	2002/01-2006/12	433MHz	F140	●	●	○	O/A	433MHz	Huf/Beru	●	●
Ferrari	F12 Berlinetta	2012/01-2022/12	433MHz	F151/ F152	●	●	○	O/A	433MHz	Huf/Beru	●	●
Ferrari	F12 tdf	2015/01-2021/12	433MHz	F151/ F152	○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	F430	2007/07-2009/10	433MHz	F131E	●	●	○	O/A	433MHz	Huf/Beru	●	●
Ferrari	F430	2005/01-2007/06	433MHz	F131E	●	●	○	O/A	433MHz	Huf/Beru	●	●
Ferrari	F8 Tributo	2019/01-2022/12	433MHz 282189	F151/ F152	○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	FF	2011/01-2020/01	433MHz	F151	●	●	○	O/A	433MHz	Huf/Beru	●	●
Ferrari	FXX	2005/01-2006/12	433MHz	F140	○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	GTC4 Lusso	2016/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	La Ferrari	2013/01-2020/12	433MHz	F150	○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	Monza SP1/SP2	2019/01-2021/12	433MHz	F151/ F152	○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	Portofino	2017/01-2021/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Ferrari	Roma	2020/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ferrari	SF90 Stralade	2020/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Fiat	124 Spider	2015/08-2021/12	433MHz	NF/J12F	○	●	○	A	433MHz	Continental	●	●
Fiat	500	2014/01-2022/12	433MHz	312	●	●	●	O/A	433MHz	Schrader	●	●
Fiat	500	2014/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500C	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500C	2014/01-2019/06	433MHz	312	●	●	●	O/A	433MHz	Schrader	●	●
Fiat	500L	2013/03-2016/12	433MHz		●	●	●	O/A	433MHz	Schrader	●	●
Fiat	500L	2012/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	500X	2014/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Fiat	Doblo	2009/01-2021/12	433MHz	223/263	●	●	●	O/A	433MHz	Schrader	●	●
Fiat	Ducato	2014/06-2024/06	433MHz	X2/50	●	●	●	O/A	433MHz	Schrader	●	●
Fiat	Freemont	2014/07-2022/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Fiat	Freemont	2011/01-2014/06	433MHz	JF	●	●	○	O/A	433MHz	Schrader	●	●
Fiat	Panda	2012/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Fiat	Punto	2005/09-2018/12	433MHz	199	○	●	○	C	433MHz	TRW	●	●
Fiat	Scudo	2016/01-2019/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Fiat	Scudo	2013/01-2019/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Fiat	Scudo	2006/01-2013/10	433MHz	G9	○	●	○	A	433MHz	Schrader	●	●
Fiat	Talento	2016/01-2022/12	433MHz	FJL/X82	○	●	○	A	433MHz	Schrader	●	●
Ford	Ecosport	2017/11-2022/12	433MHz	CR6	●	●	○	O/S	433MHz	Schrader	●	●
Ford	Ecosport	2013/06-2014/09	433MHz	B515	●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Ecosport	2013/01-2019/06	433MHz EV6T1A180CB	CBW	●	●	○	S/A	433MHz	Schrader	●	●
Ford	Edge	2016/01-2019/12	433MHz	CD389/ CD539	●	●	●	O/S/A	433MHz	Schrader	●	●
Ford	Edge	2015/01-2015/12	433MHz	CD389/ CD539	●	●	●	O/S/A	433MHz	Schrader	●	●
Ford	Edge	2020/01-2021/06	433MHz	CD389/ CD539	●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Endura	2018/01-2020/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Ford	Endura	2018/01-2018/12	433MHz		●	●	○	O/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	Escape	2018/01-2019/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Escape	2020/01-2022/12	315MHz		●	●	○	0	315MHz	Schrader	●	●
Ford	Escape	2020/01-2022/12	433MHz		●	●	○	S	433MHz	Schrader	●	●
Ford	Escape	2013/10-2014/12	315MHz	C520	●	●	●	0/S	315MHz	Schrader	●	●
Ford	Escape	2013/01-2013/09	315MHz	C520	●	●	●	S	315MHz	Schrader	●	●
Ford	Escape	2015/01-2015/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Escape	2016/01-2017/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	Everest	2006/01-2009/05	315MHz		○	●	○	S	315MHz	Continental	●	●
Ford	Everest	2009/06-2015/05	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	Everest	2016/06-2022/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Everest	2015/06-2019/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	Expedition	2018/01-2018/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
Ford	Explorer	2011/01-2015/12	315MHz	U502	●	●	●	S	315MHz	Schrader	●	●
Ford	F-150	2014/03-2019/12	433MHz	P552	●	●	●	0/S	433MHz	Schrader	●	●
Ford	F-Series	2017/01-2020/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Ford	F-Series	2015/01-2020/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Fiesta	2014/01-2019/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Ford	Fiesta	2017/01-2022/12	433MHz	CE1	●	●	○	0/S	433MHz	Schrader	●	●
Ford	Focus	2018/05-2019/12	433MHz	CGE	●	●	●	0/S/A	433MHz	Schrader	●	●
Ford	Focus	2011/01-2019/06	433MHz EV6T1A180DB	CEW/CB8	●	●	●	0/S	433MHz	Schrader	●	●
Ford	Focus	2020/01-2022/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Kuga	2014/01-2019/12	433MHz	C520	●	●	●	0/S/A	433MHz	Schrader	●	●
Ford	Mondeo	2014/10-2017/12	Snap in 433MHz	CD391	●	●	●	0/S	433MHz	Schrader	●	●
Ford	Mondeo	2013/01-2015/06	Clamp in 433MHz	CD345	●	●	○	0	433MHz	Continental	●	●
Ford	Mondeo	2007/01-2012/12	Clamp in 433MHz	CD345	●	●	○	0/A	433MHz	Continental	●	●
Ford	Mondeo	2017/09-2019/05	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Ford	Mustang	2020/01-2022/12	433MHz	S550	●	●	○	0/S/A	433MHz	Schrader	●	●
Ford	Mustang	2016/01-2019/12	433MHz	S550	●	●	●	0/S/A	433MHz	Schrader	●	●
Ford	Mustang	2015/08-2015/12	433MHz	S550	●	●	●	0/S/A	433MHz	Schrader	●	●
Ford	Mustang	2015/01-2015/07	433MHz	S550	●	●	○	0/S/A	433MHz	Schrader	●	●
Ford	PUMA	2019/11-2022/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Ranger	2015/01-2022/12	Hi Line 433MHz		●	●	○	0/S	433MHz	Schrader	●	●
Ford	Ranger	2015/01-2015/12	Lo Line 433MHz	P375	●	●	●	0/S	433MHz	Schrader	●	●
Ford	Ranger	2014/05-2014/12	433MHz	P375	○	●	○	S	433MHz	Schrader	●	●
Ford	Territory	2016/01-2016/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	Territory	2007/01-2010/12	315MHz		○	●	○	S	315MHz	Continental	●	●
Ford	Territory	2004/01-2006/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Ford	Territory	2011/01-2015/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	Transit	2010/01-2014/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Ford	Transit	2013/06-2014/12	433MHz	V363	○	●	○	S	433MHz	Schrader	●	●
Ford	Transit	2015/01-2015/12	315MHz		●	●	○	0/S	315MHz	Schrader	●	●
Ford	Transit	2019/01-2019/12	433MHz	V363	●	●	○	0/S	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ford	Transit	2017/01-2020/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Ford	Transit	2016/01-2016/12	315MHz		●	●	○	O/S	315MHz	Schrader	●	●
Ford	Transit Custom	2013/01-2019/12	315MHz	V363	○	●	○	S/A	315MHz	Schrader	●	●
Ford	Transit Custom	2013/09-2019/12	433MHz	V363	●	●	○	O/S/A	433MHz	Schrader	●	●
Ford	Transit Custom	2019/01-2021/12	Trailer 433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Ford	Transit Van	2019/01-2021/12	Trailer 433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Ford	Transit Van	2013/01-2019/12	315MHz	V363	○	●	○	S/A	315MHz	Schrader	●	●
Foton	Cargo Van	2018/01-2019/12	433MHz		●	●	○	S	433MHz	TTE	●	●
Foton	Sauvana	2015/01-2020/12	433MHz		●	●	○	S	433MHz	TTE	●	●
Foton	Tunland	2011/01-2021/12	433MHz		●	●	○	S	433MHz	TTE	●	●
Foton	Viuw CS2	2014/01-2018/12	433MHz		●	●	○	S	433MHz	TTE	●	●
GMC	Acadia	2018/09-2022/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
GMC	Acadia	2016/11-2018/08	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
GMC	Denali	2017/01-2017/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Denali	2014/01-2016/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Denali	2020/01-2021/12	315Mhz 13512346		○	●	○	C	315MHz	Schrader	●	●
GMC	Denali	2018/01-2020/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2010/01-2011/12	Clamp in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2014/01-2014/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2015/01-2016/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2018/01-2022/12	433MHz 13516165		●	●	●	O/S	433MHz	Schrader	●	●
GMC	Sierra	2009/01-2013/12	Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2007/01-2008/12	SCH Snap in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2007/01-2007/12	SCH Clamp in 315MHz		●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2017/01-2021/12	315MHz	XL7	●	●	●	O/S	315MHz	Schrader	●	●
GMC	Sierra	2007/01-2007/12	TRW Clamp in 315MHz		●	●	●	O/S	315MHz	TRW	●	●
Geely	Coolray	2019/09-2022/12	433MHz		●	●	○	O	433MHz	Baolong	●	●
Geely	EMGRAND	2016/01-2019/12	433MHz		●	●	○	O	433MHz	Continental	●	●
Geely	GC 6	2015/01-2019/12	433MHz		●	●	○	O	433MHz	Dias	●	●
Geely	X7	2017/01-2019/12	433MHz		●	●	○	O	433MHz	Dias	●	●
GreatWall	Steed Pick Up	2014/01-2021/12	433MHz		●	●	○	O	433MHz	SAT	●	●
GreatWall	Voleex C20R	2014/01-2016/12	433MHz		●	●	○	O	433MHz	SAT	●	●
GreatWall	Voleex C30	2015/01-2017/12	SAT 433MHz		●	●	○	O	433MHz	SAT	●	●
GreatWall	Wingle	2014/01-2017/12	433MHz		●	●	○	O	433MHz	SAT	●	●
GreatWall	Wingle 5	2011/01-2015/12	433MHz		○	●	○	S	433MHz	SAT	●	●
HSV	Clubsport R8	2014/01-2019/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
HSV	G	2014/01-2016/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
HSV	GTC	2014/01-2018/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
HSV	GTS	2017/01-2019/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
HSV	GTSR	2017/01-2019/12	433MHz		○	●	○	A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
HSV	Grange	2011/01-2013/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
HSV	Grange	2014/01-2017/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
HSV	Maloo R8 LSA	2014/01-2019/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
HSV	Senator Signature	2010/01-2012/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
HSV	Senator Signature	2016/01-2019/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
HSV	SportCats	2018/01-2020/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
Haval	Dargo	2020/09-2022/12	433MHz 3641101XKN01 A		●	●	○	0	433MHz	Schrader	●	●
Haval	Dargo	2020/09-2022/12	433MHz 3641101BKN01 A		●	●	○	0/A	433MHz	SAT	●	●
Haval	F7	2021/01-2022/12	433MHz		●	●	○	0	433MHz	Dias	●	●
Haval	H1	2014/01-2021/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Haval	H2	2014/01-2018/05	433MHz 3641100XKU00 A		●	●	○	0	433MHz	Schrader	●	●
Haval	H6	2011/01-2015/12	433MHz 3641100XKZ16 A		●	●	○	0	433MHz	SAT	●	●
Haval	H6	2016/01-2021/12	433MHz 3641100XKZ16 A		●	●	○	0	433MHz	SAT	●	●
Haval	H8	2013/01-2019/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Haval	H9	2020/01-2021/08	433MHz		●	●	○	0	433MHz	Schrader	●	●
Haval	Jolion	2021/01-2022/12	433MHz 3641101XKN01 A		●	●	○	0	433MHz	Schrader	●	●
Haval	Jolion	2021/01-2022/12	433MHz 3641100BKR02 A		●	●	○	0	433MHz	Dias	●	●
Holden	Acadia	2018/01-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Holden	Astra H	2004/01-2010/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Holden	Astra J	2015/01-2015/09	433MHz	GM P3400	●	●	●	0/S	433MHz	Schrader	●	●
Holden	Astra J	2009/01-2011/09	433MHz	GM P3400	●	●	●	0	433MHz	Schrader	●	●
Holden	Astra J	2011/10-2014/05	433MHz	GM P3400/ GM A3300	●	●	●	0	433MHz	Schrader	●	●
Holden	Astra J	2014/06-2014/12	433MHz	GM P3400	●	●	●	0	433MHz	Schrader	●	●
Holden	Astra K	2015/10-2020/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Holden	Barina	2011/01-2018/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Holden	Caprice	2014/01-2017/12	13581558 315MHz		○	●	○	C	315MHz	Schrader	●	●
Holden	Caprice	2011/01-2013/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Holden	Caprice	2014/01-2017/12	315MHz		●	●	●	0/S	315MHz	Schrader	●	●
Holden	Captiva	2006/06-2008/12	433MHz	C100	●	●	●	0/S	433MHz	Schrader	●	●
Holden	Captiva	2009/01-2011/12	433MHz	C100	●	●	●	0/S	433MHz	Schrader	●	●
Holden	Captiva	2012/01-2015/12	433MHz	C100	●	●	●	0/S	433MHz	Schrader	●	●
Holden	Captiva	2016/01-2019/12	433MHz		●	●	●	0/S	433MHz	Schrader	●	●
Holden	Cascada	2013/01-2014/05	433MHz		●	●	●	0	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Holden	Cascada	2014/06-2019/12	433MHz		●	●	●	O/A	433MHz	Schrader	●	●
Holden	Colorado	2018/01-2021/12	315Mhz		●	●	○	O	315MHz	Schrader	●	●
Holden	Colorado	2016/01-2016/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Colorado	2011/01-2013/12	315MHz		○	●	○	C	315MHz	Schrader	●	●
Holden	Colorado	2011/07-2012/12	433MHz	Gmi700	●	●	●	O/S	433MHz	Schrader	●	●
Holden	Colorado	2013/01-2017/12	433MHz	Gmi700	●	●	●	O/S	433MHz	Schrader	●	●
Holden	Colorado	2014/01-2014/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Colorado	2015/01-2015/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Colorado	2017/01-2019/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Commodore	2010/01-2013/12	433MHz	VE	○	●	○	S	433MHz	Schrader	●	●
Holden	Commodore	2013/01-2017/12	315MHz	VF	●	●	●	O/S	315MHz	Schrader	●	●
Holden	Commodore	2018/01-2020/12	433MHz	ZB	●	●	●	O/A	433MHz	Schrader	●	●
Holden	Corvette	2019/01-2019/12	433MHz		●	●	●	O/A	433MHz	Schrader	●	●
Holden	Equinox	2017/06-2020/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2011/01-2012/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2010/01-2010/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2009/01-2009/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2008/01-2008/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2013/01-2015/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2007/01-2007/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2016/01-2016/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Equinox	2017/01-2017/05	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Spark	2009/07-2012/12	433MHz	M1JC	○	●	○	S	433MHz	Schrader	●	●
Holden	Spark	2013/01-2014/12	433MHz	M1JC	●	●	●	O/S	433MHz	Schrader	●	●
Holden	Spark	2015/01-2015/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Holden	Spark	2016/01-2016/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Holden	Spark	2017/01-2019/12	315MHz		●	●	○	S	315MHz	Schrader	●	●
Holden	Statesman	2013/01-2017/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Holden	Trailblazer	2001/01-2005/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Holden	Trailblazer	2006/01-2006/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
Holden	Trailblazer	2006/01-2008/12	433MHz	GMT360	●	●	●	S	433MHz	Schrader	●	●
Holden	Trailblazer	2007/01-2009/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
Holden	Trailblazer	2009/01-2009/12	433MHz		●	●	●	S	433MHz	Schrader	●	●
Holden	Trailblazer	2012/01-2013/12	433MHz 20922901		●	●	●	O/S	433MHz	Schrader	●	●
Holden	Trailblazer	2013/01-2014/12	433MHz 20925925		○	●	○	S	433MHz	Schrader	●	●
Holden	Trailblazer	2016/01-2019/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Trax	2015/01-2019/12	433MHz	G1UC	●	●	●	O/S	433MHz	Schrader	●	●
Holden	Trax	2016/01-2016/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Trax	2013/01-2014/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Trax	2013/01-2014/12	433MHz	G1UC	●	●	●	O/S	433MHz	Schrader	●	●
Holden	Trax	2012/01-2012/12	433MHz	G1UC	○	●	○	S	433MHz	Schrader	●	●
Holden	Trax	2015/01-2015/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	UTE	2016/01-2018/12	433MHz		●	●	●	O/S	433MHz	Schrader	●	●
Holden	UTE	2011/01-2015/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Holden	Volt	2013/01-2014/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Holden	Volt	2011/01-2012/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	Volt	2010/01-2010/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Holden	Volt	2015/01-2015/12	315MHz		●	●	●	O/S	315MHz	Schrader	●	●
Holden	WM Caprice	2007/01-2012/12	433MHz	WM	○	●	○	C	433MHz	Schrader	●	●
Honda	Accord	2013/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Accord	2008/01-2012/12	315MHz		●	●	○	O	315MHz	Pacific	●	●
Honda	CR-V	2010/07-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	CR-V	2012/01-2014/12	315MHz		●	●	○	O	315MHz	Continental	●	●
Honda	CR-V	2007/01-2011/12	Alloy/Steel 315MHz		●	●	○	O	315MHz	Pacific	●	●
Honda	CR-Z	2010/01-2017/12	315MHz		●	●	○	O	315MHz	TRW	●	●
Honda	CR-Z	2010/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	City	2014/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	Civic	2016/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Honda	Civic	2012/01-2014/12	315MHz		●	●	○	O	315MHz	TRW	●	●
Honda	HR-V	2014/09-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	Insight	2009/06-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	Jazz	2014/01-2020/12	Direct 433MHz		●	●	○	O	433MHz	Continental	●	●
Honda	Jazz	2014/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Honda	Legend	2015/01-2020/12	315MHz	Hybrid	●	●	○	O	315MHz	TRW	●	●
Honda	NSX	2016/01-2021/06	Direct 433MHz		●	●	○	O	433MHz	Continental	●	●
Honda	Odyssey	2014/01-2017/12	315MHz		○	●	○	C	315MHz	TRW	●	●
Honda	Odyssey	2017/01-2020/12	433MHz		●	●	○	O	433MHz	Continental	●	●
Hummer	H3	2007/01-2012/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
Hummer	H3	2005/01-2006/12	315MHz		●	●	●	S	315MHz	Schrader	●	●
Hyundai	Accent	2011/01-2014/12	315MHz	RB	●	●	○	O	315MHz	Continental	●	●
Hyundai	Accent	2005/01-2010/12	315MHz	MC	●	●	○	O	315MHz	TRW	●	●
Hyundai	Accent	2014/01-2020/06	Lo Line 433MHz	RB	●	●	○	O	433MHz	Continental	●	●
Hyundai	Accent	2011/04-2021/12	Hi Line 433MHz	RB	●	●	○	O	433MHz	Continental	●	●
Hyundai	Carens	2019/01-2019/12	RP 433MHz		●	●	○	O	433MHz	Continental	●	●
Hyundai	Elantra	2010/01-2012/12	315MHz	FD	●	●	○	O	315MHz	Continental	●	●
Hyundai	Elantra	2014/01-2018/12	433MHz	MD/UD	●	●	○	O	433MHz	TRW	●	●
Hyundai	Elantra	2013/10-2019/12	Lo Line 315MHz		●	●	○	O/A	315MHz	TRW	●	●
Hyundai	Elantra	2013/01-2013/10	315MHz		●	●	○	O	315MHz	TRW	●	●
Hyundai	Elantra	2015/01-2020/12	433MHz	AD	●	●	○	O	433MHz	Continental	●	●
Hyundai	Equus	2013/03-2016/06	Hi Line 315MHz	VI	●	●	○	O	315MHz	Continental	●	●
Hyundai	Genesis	2013/01-2017/12	433MHz	DH	●	●	○	O/A	433MHz	Continental	●	●
Hyundai	Genesis	2008/09-2014/12	Conti 315MHz	BH	●	●	○	O	315MHz	Continental	●	●
Hyundai	Genesis	2008/01-2014/12	TRW 315MHz	BH	●	●	○	O	315MHz	TRW	●	●
Hyundai	Genesis G70	2017/01-2017/12	433MHz	IK	●	●	○	O	433MHz	Schrader	●	●
Hyundai	Genesis G70	2021/01-2022/12	433MHz	IK	●	●	○	C	433MHz	Schrader	●	●
Hyundai	Genesis G70	2018/01-2020/12	433MHz	IK	●	●	○	C	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Hyundai	Genesis G80	2020/01-2022/12	433MHz	DH	●	●	○	A	433MHz	Continental	●	●
Hyundai	Genesis G80	2016/07-2019/12	433MHz	DH	●	●	○	O	433MHz	Continental	●	●
Hyundai	Genesis G80	2021/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Hyundai	Genesis Sedan	2009/01-2014/12	315MHz	BH	●	●	○	O	315MHz	TRW	●	●
Hyundai	H-1	2014/01-2019/12	433MHz	HR	●	●	○	O	433MHz	Continental	●	●
Hyundai	Ioniq	2016/01-2022/12	433MHz	AE	●	●	○	O	433MHz	Continental	●	●
Hyundai	Ioniq 5	2022/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Hyundai	Ioniq 5	2020/01-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Hyundai	Kona	2017/01-2022/12	433MHz		●	●	○	A/O	433MHz	Continental	●	●
Hyundai	Nexo	2018/04-2019/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Hyundai	Nexo	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Hyundai	Palisade	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Hyundai	Palisade	2019/01-2019/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Hyundai	Santa Fe	2018/03-2022/12	433MHz	TM/TMA	●	●	○	A	433MHz	Schrader	●	●
Hyundai	Santa Fe	2009/06-2012/12	315MHz	CM	●	●	○	O	315MHz	Lear	●	●
Hyundai	Santa Fe	2006/01-2008/12	433MHz	CM	●	●	○	O	433MHz	Lear	●	●
Hyundai	Santa Fe	2013/04-2017/03	433MHz	DM/DMI	●	●	○	O	433MHz	Continental	●	●
Hyundai	Sonata	2009/12-2014/05	315MHz 529332M000	YF	●	●	○	O	315MHz	Continental	●	●
Hyundai	Sonata	2010/01-2010/12	315MHz	YF	●	●	○	O	315MHz	TRW	●	●
Hyundai	Sonata	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Hyundai	Sonata	2014/04-2019/12	Hi Line 433MHz	LF/LFA	●	●	○	O	433MHz	Schrader	●	●
Hyundai	Staria	2021/03-2027/12	433MHz		●	●	○	C	433MHz	Schrader	●	●
Hyundai	Tucson	2014/06-2015/12	315MHz	ix	●	●	○	O	315MHz	TRW	●	●
Hyundai	Tucson	2021/01-2021/09	433MHz Hi Line	TL	●	●	○	A	433MHz	Schrader	●	●
Hyundai	Tucson	2014/09-2015/12	315MHz	LM	●	●	○	O	315MHz	TRW	●	●
Hyundai	Tucson	2015/01-2015/12	433MHz	TL/TLE	●	●	○	O	433MHz	Schrader	●	●
Hyundai	Tucson	2010/01-2013/07	315MHz	LM	●	●	○	O	315MHz	TRW	●	●
Hyundai	Tucson	2015/05-2020/12	433MHz Hi Line	TL	●	●	○	O	433MHz	Schrader	●	●
Hyundai	Veloster	2011/03-2019/06	433MHz	FS	●	●	○	O	433MHz	Schrader	●	●
Hyundai	Veloster	2011/01-2019/12	315MHz	FS	●	●	○	O/A	315MHz	Schrader	●	●
Hyundai	Veloster	2019/01-2021/12	433MHz		●	●	○	O	433MHz	Continental	●	●
Hyundai	Venue	2020/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Hyundai	i10	2016/01-2019/12	PA 433MHz		●	●	○	O	433MHz	Continental	●	●
Hyundai	i20	2021/01-2021/12	433MHz	GB	●	●	○	A	433MHz	Schrader	●	●
Hyundai	i20	2014/10-2020/12	433MHz	GB	●	●	○	O/A	433MHz	Schrader	●	●
Hyundai	i20n	2021/01-2021/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Hyundai	i30	2016/08-2022/12	433MHz	PD/Pde	●	●	○	O	433MHz	Continental	●	●
Hyundai	i30	2014/03-2019/12	433MHz	GD	●	●	○	O/A	433MHz	Continental	●	●
Hyundai	i30	2021/01-2021/12	433MHz	CN7	●	●	○	A	433MHz	Continental	●	●
Hyundai	i30	2017/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Hyundai	i30	2007/05-2014/03	433MHz	FD/Fde	●	●	○	O	433MHz	Continental	●	●
Hyundai	i40	2017/01-2019/12	433MHz	IF	●	●	○	O	433MHz	Continental	●	●
Hyundai	i40	2014/04-2020/12	433MHz	VF	●	●	○	O/A	433MHz	TRW	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Hyundai	i40	2011/01-2014/03	433MHz	VF	●	●	○	0	433MHz	TRW	●	●
Hyundai	iLoad	2014/01-2021/12	FQ 433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	iMax	2018/01-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Hyundai	iMax	2015/01-2016/12	433MHz	TQ	●	●	○	0	433MHz	Continental	●	●
Hyundai	ix35	2014/03-2016/12	433MHz	EL	●	●	○	0	433MHz	TRW	●	●
Hyundai	ix35	2017/01-2019/12	433MHz	EL	●	●	○	A	433MHz	TRW	●	●
Infiniti	EX Series	2010/04-2018/09	315MHz	J50	●	●	○	0	315MHz	Pacific	●	●
Infiniti	EX Series	2007/01-2010/03	315MHz	J50	●	●	○	0	315MHz	Pacific	●	●
Infiniti	FX Series	2010/09-2019/09	315MHz	S51	●	●	○	0	315MHz	Pacific	●	●
Infiniti	FX Series	2007/07-2010/08	315MHz	S51	●	●	○	0	315MHz	Pacific	●	●
Infiniti	G Series	2007/01-2010/03	315MHz	V36	●	●	○	0	315MHz	Pacific	●	●
Infiniti	G Series	2010/04-2015/12	315MHz	V36	●	●	○	0	315MHz	Pacific	●	●
Infiniti	M Series	2011/01-2013/12	315MHz	Y51	●	●	○	0	315MHz	Pacific	●	●
Infiniti	M Series	2008/01-2010/12	315MHz		○	●	○	C	315MHz	Pacific	●	●
Infiniti	M Series	2006/01-2010/12	315MHz	Y50	●	●	○	0	315MHz	Schrader	●	●
Infiniti	Q30	2015/01-2019/12	433MHz		●	●	○	0/A	433MHz	Pacific	●	●
Infiniti	Q50	2013/01-2021/06	433MHz	L53H/D53H/V37	●	●	○	0	433MHz	Continental	●	●
Infiniti	Q50	2013/01-2015/12	315MHz	V37	●	●	○	0	315MHz	Continental	●	●
Infiniti	Q60	2016/05-2021/12	433MHz	CV37	●	●	○	0	433MHz	Continental	●	●
Infiniti	Q60	2013/07-2016/06	433MHz	L53A/CV36	●	●	○	0	433MHz	Pacific	●	●
Infiniti	Q60	2013/01-2017/12	315MHz	CV36/HV36	●	●	○	0	315MHz	Pacific	●	●
Infiniti	Q70	2013/01-2019/12	PAC 433MHz		●	●	○	0	433MHz	Pacific	●	●
Infiniti	Q70	2013/01-2019/12	315MHz	Y51	●	●	○	0	315MHz	Pacific	●	●
Infiniti	Q70	2017/01-2019/12	VDO 433MHz		●	●	○	0	433MHz	Continental	●	●
Infiniti	QX30	2016/03-2019/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Infiniti	QX50	2018/01-2019/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Infiniti	QX70	2013/01-2019/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Infiniti	QX70	2014/01-2020/06	PAC 433MHz	P53C/S51	●	●	○	0	433MHz	Pacific	●	●
Infiniti	QX80	2013/01-2022/12	433MHz	Z62	●	●	○	0	433MHz	Pacific	●	●
Infiniti	QX80	2014/01-2016/12	315MHz	Z62	●	●	○	0	315MHz	Pacific	●	●
Infiniti	QX80	2017/01-2021/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
Isuzu	D-Max	2007/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Isuzu	D-Max	2020/09-2022/12	SCH 433MHz		○	●	○	A	433MHz	Schrader	●	●
Isuzu	MU-X	2016/11-2021/06	433MHz		○	●	○	C	433MHz	Baolong	●	●
Jaguar	E-Pace	2017/01-2022/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Pace	2015/01-2022/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	2012/01-2015/12	433MHz	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	2020/01-2020/12	433MHz	X161	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	2016/01-2021/06	433MHz	X152	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	F-Type	2012/01-2020/12	433MHz	F52	○	●	○	C	433MHz	Continental	●	●
Jaguar	I-Pace	2017/01-2023/06	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jaguar	S-Type	1998/10-2011/08	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jaguar	Super V8	2005/01-2009/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Jaguar	X-Type	2007/01-2009/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XE	2015/01-2015/03	433MHz	X760	●	●	○	0/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Jaguar	XE	2015/01-2022/12	GX631A159AA 433MHz	X760	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XF	2015/06-2022/12	433MHz	X260	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XF	2007/01-2019/12	433MHz	X250	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	2016/01-2022/12	433MHz	X351	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	2014/03-2015/12	433MHz	X351	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	2010/01-2020/12	KR5S18005202 0A 433MHz		●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XJ	2002/10-2009/12	433MHz	X350	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XK	2014/03-2019/12	315MHz	X150	●	●	○	0/A	315MHz	Continental	●	●
Jaguar	XK	2005/09-2015/12	433MHz	X150	●	●	○	0/A	433MHz	Continental	●	●
Jaguar	XKR	2006/01-2014/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Jeep	Cherokee	2005/01-2013/12	433MHz 56029359AC	KK	●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Cherokee	2018/01-2018/12	433MHz	KL	●	●	○	A	433MHz	TRW	●	●
Jeep	Cherokee	2013/10-2015/11	433MHz	KL	●	●	●	0/A	433MHz	TRW	●	●
Jeep	Cherokee	2015/12-2017/12	433MHz	KL	●	●	●	0/A	433MHz	TRW	●	●
Jeep	Cherokee	2019/01-2021/12	433MHz	KL	●	●	○	A	433MHz	TRW	●	●
Jeep	Commander	2006/01-2007/12	433MHz	XK	●	●	●	0/A	433MHz	Continental	●	●
Jeep	Commander	2008/01-2011/12	433MHz	XK	●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Commander	2006/01-2007/12	315MHz	XK	●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Compass	2012/01-2016/12	315MHz	MK49	●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Compass	2014/01-2017/12	Continental 315MHz	MK49	●	●	●	0/A	315MHz	Continental	●	●
Jeep	Compass	2015/01-2015/12	433MHz		●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Compass	2017/01-2017/12	433MHz	551	●	●	●	0/A	433MHz	Continental	●	●
Jeep	Compass	2017/01-2017/12	433MHz	MP/MX	●	●	●	0/A	433MHz	Continental	●	●
Jeep	Compass	2019/01-2019/12	Continental 315MHz	MK49	●	●	○	A	315MHz	Continental	●	●
Jeep	Compass	2019/01-2022/12	433MHz	551	●	●	○	A	433MHz	Continental	●	●
Jeep	Compass	2018/01-2018/12	433MHz	551	●	●	○	0/A	433MHz	Continental	●	●
Jeep	Compass	2010/01-2011/12	315MHz	MK49	●	●	●	0/A	315MHz	Continental	●	●
Jeep	Compass	2018/01-2018/12	Continental 315MHz	MK49	●	●	○	0/A	315MHz	Continental	●	●
Jeep	Gladiator	2019/11-2022/12	MRXAG4WA5 433MHz		●	●	○	A	433MHz	Schrader	●	●
Jeep	Grand Cherokee	2016/01-2017/12	433MHz	WK	●	●	●	0/A	433MHz	Continental	●	●
Jeep	Grand Cherokee	2006/06-2010/12	433MHz	WH	●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Grand Cherokee	2006/01-2007/12	315MHz	WK	●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Grand Cherokee	2008/01-2011/12	315MHz	WK	●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Grand Cherokee	2010/07-2010/12	433MHz	WK	●	●	●	0/A	433MHz	Schrader	●	●
Jeep	Grand Cherokee	2014/01-2015/12	433MHz	WK74	●	●	●	0	433MHz	Schrader	●	●
Jeep	Grand Cherokee	2011/01-2011/12	433MHz	WK74	●	●	●	0	433MHz	Schrader	●	●
Jeep	Grand Cherokee	2012/01-2013/12	433MHz	WK74	●	●	●	0	433MHz	Schrader	●	●
Jeep	Grand Cherokee	2005/01-2006/05	433MHz		●	●	●	0	433MHz	Continental	●	●
Jeep	Grand Cherokee	2001/01-2004/12	433MHz	WK/WJ	●	●	○	S	433MHz	Schrader	●	●
Jeep	Liberty	2010/01-2012/12	315MHz	KK	●	●	●	0/A	315MHz	Schrader	●	●
Jeep	Liberty	2007/01-2009/12	315MHz	KJ	●	●	●	0/A	315MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Jeep	Liberty	2006/01-2012/12	433MHz	KK	●	●	●	O/A	433MHz	Schrader	●	●
Jeep	Liberty	2005/01-2006/12	315MHz	KJ	●	●	○	A	315MHz	Schrader	●	●
Jeep	Liberty	2002/01-2004/12	433MHz	KJ	●	●	○	A	433MHz	Schrader	●	●
Jeep	Patriot	2018/01-2019/06	315MHz		●	●	○	A	315MHz	Schrader	●	●
Jeep	Patriot	2012/01-2017/12	315MHz		●	●	○	O/A	315MHz	Schrader	●	●
Jeep	Patriot	2014/12-2017/12	433MHz	MK74	●	●	●	O/A	433MHz	Schrader	●	●
Jeep	Patriot	2011/01-2016/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Jeep	Patriot	2009/01-2014/12	315MHz	MK	●	●	●	O/A	315MHz	Schrader	●	●
Jeep	Renegade	2015/01-2016/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
Jeep	Renegade	2019/01-2019/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Jeep	Renegade	2018/01-2018/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Jeep	Renegade	2017/01-2017/12	433MHz		●	●	●	O/A	433MHz	Continental	●	●
Jeep	Wrangler	2018/01-2021/06	433MHz	JL	●	●	○	A	433MHz	Schrader	●	●
Jeep	Wrangler	2007/01-2009/12	315MHz	JK	●	●	●	O/A	315MHz	Schrader	●	●
Jeep	Wrangler	2008/06-2010/12	433MHz	JK	●	●	●	O/A	433MHz	Schrader	●	●
Jeep	Wrangler	2010/01-2012/12	315MHz	JK	●	●	●	O/A	315MHz	Schrader	●	●
Jeep	Wrangler	2010/01-2013/12	433MHz	JK72	●	●	●	O/A	433MHz	Schrader	●	●
Jeep	Wrangler	2013/01-2014/12	433MHz	JK	●	●	●	O/A	433MHz	Schrader	●	●
Jeep	Wrangler	2014/01-2017/12	433MHz	JL	●	●	●	O/A	433MHz	Schrader	●	●
KIA	Carens	2012/01-2020/12	433MHz	RP/UN	●	●	○	O/A	433MHz	Continental	●	●
KIA	Carnival	2005/01-2014/12	315MHz	YP	●	●	○	O	315MHz	Lear	●	●
KIA	Carnival	2016/01-2018/12	433MHz	YP/VQ	●	●	○	O	433MHz	Continental	●	●
KIA	Carnival	2019/01-2020/12	433MHz		●	●	○	C	433MHz	Schrader	●	●
KIA	Carnival	2020/01-2022/12	433MHz	KA4	●	●	○	A	433MHz	Continental	●	●
KIA	Ceed	2012/03-2018/06	433MHz	JD	●	●	○	O	433MHz	Continental	●	●
KIA	Ceed	2018/05-2019/12	433MHz	CD	●	●	○	O/A	433MHz	Pacific	●	●
KIA	Ceed	2020/01-2020/12	433MHz	CD	●	●	○	A	433MHz	Pacific	●	●
KIA	Cerato	2012/01-2013/12	YD 315MHz		●	●	○	O	315MHz	Continental	●	●
KIA	Cerato	2015/01-2016/12	BD 433MHz		●	●	○	O	433MHz	Continental	●	●
KIA	Cerato	2017/01-2018/12	315MHz YD		●	●	○	O	315MHz	TRW	●	●
KIA	Cerato	2019/01-2021/12	433MHz	BD	●	●	○	A	433MHz	Pacific	●	●
KIA	Cerato	2022/01-2022/12	433MHz	BD	●	●	○	A	433MHz	Pacific	●	●
KIA	Cerato	2019/01-2019/12	315MHz YD		●	●	○	C	315MHz	TRW	●	●
KIA	K3	2021/07-2021/12	433MHz	BD	●	●	○	A	433MHz	Pacific	●	●
KIA	Optima	2013/09-2015/12	315MHz	TF/QF	●	●	○	O	315MHz	Continental	●	●
KIA	Optima	2010/07-2013/09	315MHz	TF/QF	●	●	○	O/A	315MHz	Continental	●	●
KIA	Optima	2015/09-2022/12	433MHz	JF/JFA	●	●	○	O/A	433MHz	Continental	●	●
KIA	Optima	2014/03-2019/12	433MHz	JF	●	●	○	O/A	433MHz	Continental	●	●
KIA	Picanto	2017/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
KIA	Picanto	2011/01-2017/12	TA 433MHz		●	●	○	O	433MHz	Continental	●	●
KIA	Pro Ceed	2020/01-2021/06	433MHz	CD	●	●	○	A	433MHz	Pacific	●	●
KIA	Pro Ceed	2012/03-2018/06	433MHz	JD	●	●	○	O	433MHz	Continental	●	●
KIA	Pro Ceed	2022/01-2022/12	433MHz	CD	●	●	○	O/A	433MHz	Pacific	●	●
KIA	Pro Ceed	2018/05-2019/12	433MHz	CD	●	●	○	O/A	433MHz	Pacific	●	●
KIA	Quoris	2012/06-2019/12	433MHz		●	●	○	O	433MHz	Schrader	●	●
KIA	Rio	2016/12-2020/06	Indirect		○	○	○	S	N/A	N/A	Indirect	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
KIA	Rio	2014/03-2019/12	433MHz	UB	●	●	○	O/A	433MHz	TRW	●	●
KIA	Rio	2011/06-2017/12	315MHz	UB	●	●	○	0	315MHz	TRW	●	●
KIA	Rio	2017/01-2021/12	433MHz	QB	●	●	○	O/A	433MHz	Continental	●	●
KIA	Rondo	2014/03-2019/12	433MHz		●	●	○	A	433MHz	Continental	●	●
KIA	Seltos	2019/01-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
KIA	Sorento	2020/01-2022/12	433MHz	MQ4	●	●	○	A	433MHz	Continental	●	●
KIA	Sorento	2017/08-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
KIA	Sorento	2009/01-2014/05	315MHz	XM	●	●	○	0	315MHz	Continental	●	●
KIA	Sorento	2014/03-2019/12	433MHz	UM	●	●	○	0	433MHz	Continental	●	●
KIA	Sorento	2014/06-2015/12	315MHz	XM/UM	●	●	○	0	315MHz	Continental	●	●
KIA	Sorento	2015/01-2017/07	433MHz		●	●	○	0	433MHz	Continental	●	●
KIA	Soul	2019/01-2019/12	433MHz	PS	●	●	○	A	433MHz	Schrader	●	●
KIA	Soul	2013/08-2018/12	433MHz	PS	●	●	○	0	433MHz	Schrader	●	●
KIA	Soul	2009/01-2013/10	315MHz	AM	●	●	○	0	315MHz	Continental	●	●
KIA	Soul EV	2019/01-2019/12	433MHz	PS EV	●	●	○	A	433MHz	Schrader	●	●
KIA	Soul EV	2014/06-2018/12	433MHz	PS EV	●	●	○	0	433MHz	Schrader	●	●
KIA	Sportage	2015/11-2021/06	433MHz	QL/QLE	●	●	○	O/A	433MHz	Continental	●	●
KIA	Sportage	2010/01-2014/05	315MHz	SL	●	●	○	O/A	315MHz	TRW	●	●
KIA	Sportage	2014/06-2015/12	315MHz	SL	●	●	○	O/A	315MHz	TRW	●	●
KIA	Sportage	2021/01-2023/12	433MHz 52940L1100		●	●	○	A	433MHz	Continental	●	●
KIA	Stinger	2017/06-2017/12	433MHz	CK	●	●	○	0	433MHz	Schrader	●	●
KIA	Stinger	2018/01-2022/12	433MHz	CK	●	●	○	A	433MHz	Schrader	●	●
Lamborghini	Aventador	2011/01-2022/12	433MHz	LB834	○	●	○	A	433MHz	Huf/Beru	●	●
Lamborghini	Gallardo	2007/01-2014/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Lamborghini	Huracan	2014/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Lamborghini	Murcielago	2002/01-2015/12	433MHz	LB824	○	●	○	A	433MHz	Huf/Beru	●	●
Lamborghini	One off	2016/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Lamborghini	Reventon	2007/01-2010/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Lamborghini	Sian	2020/01-2022/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Lamborghini	Urus	2018/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Land Rover	Defender	2019/01-2022/12	433MHz LR066378		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Defender	1997/01-2019/12	KR5S18005202 0A 433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Discovery	2009/01-2022/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Discovery	2004/11-2009/11	KR5S12278000 2 433MHz	Di092	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Discovery	2013/01-2013/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Land Rover	Discovery	2004/01-2017/01	KR5S18005202 0 433MHz	Di4	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	2020/01-2022/12	433MHz LR070840		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Discovery Sport	2014/01-2022/12	433MHz	L550	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	FreeLander	2006/01-2022/06	433MHz	Fr132	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover	2005/01-2009/12	433MHz	L322	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover	2015/06-2022/12	433MHz	D6, Ra5	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover	2014/03-2019/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Land Rover	Range Rover	2013/01-2013/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Land Rover	Range Rover	2010/01-2015/12	433MHz	L322	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover	2002/01-2004/12	433MHz	L30	●	●	○	O/A	433MHz	Huf/Beru	●	●
Land Rover	Range Rover Evoque	2011/01-2019/12	BH521A159AA 433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Grand Evoque	2017/01-2020/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	2005/01-2009/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	2020/01-2020/12	433MHz	L461	●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	2014/01-2015/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	2010/01-2013/08	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Sport	2016/01-2022/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Land Rover	Range Rover Velar	2017/01-2023/06	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Lexus	CT Series	2010/12-2022/12	433MHz	080A	●	●	○	0	433MHz	Pacific	●	●
Lexus	ES Series	2006/01-2012/05	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	ES Series	2012/06-2018/05	433MHz	980L	●	●	○	0	433MHz	Pacific	●	●
Lexus	ES Series	2018/06-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	GS Series	2005/01-2011/12	433MHz	GS32	●	●	○	0	433MHz	Pacific	●	●
Lexus	GS Series	2012/01-2022/12	433MHz	920L	●	●	○	0	433MHz	Pacific	●	●
Lexus	IS Series	2013/04-2022/12	C210 433MHz	030L/400A/720A/XE30	●	●	○	0	433MHz	Pacific	●	●
Lexus	IS Series	2006/01-2013/03	433MHz	XE20	●	●	○	0	433MHz	Pacific	●	●
Lexus	LC Series	2017/01-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	LS Series	2006/08-2012/09	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	LS Series	2017/10-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	LS Series	2012/10-2017/09	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	LX Series	2015/10-2021/12	C215 433MHz	URJ	●	●	○	0	433MHz	Pacific	●	●
Lexus	LX Series	2012/06-2022/12	C210 433MHz	URJ	●	●	○	0	433MHz	Pacific	●	●
Lexus	NX Series	2014/01-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	RC Series	2014/01-2022/12	433MHz	XC1/720A	●	●	○	0	433MHz	Pacific	●	●
Lexus	RX Series	2014/01-2021/12	C210 433MHz		●	●	○	0	433MHz	Pacific	●	●
Lexus	SC Series	2006/08-2010/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
Lexus	UX Series	2018/01-2023/12	C215 433MHz	URJ	●	●	○	0	433MHz	Pacific	●	●
Lotus	3 Eleven	2014/01-2019/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Elise	2008/01-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Lotus	Evora	2009/06-2021/12	433MHz	Eagle	○	●	○	A	433MHz	Schrader	●	●
Lotus	Exige	2000/09-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
MAXUS	D90	2017/08-2019/05	433MHz		●	●	○	0	433MHz	Dias	●	●
MAXUS	D90	2019/06-2020/04	433MHz		●	●	○	0	433MHz	Dias	●	●
MAXUS	D90 PRO	2020/04-2022/12	433MHz		●	●	○	0	433MHz	Dias	●	●
MAXUS	D90 PRO	2016/06-2020/12	433MHz (C00047579)		●	●	○	0	433MHz	Dias	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
MAXUS	G10	2014/01-2022/12	433MHz C00047579		●	●	○	0	433MHz	Dias	●	●
MAXUS	G10	2014/01-2022/12	433MHz GC91B50		●	●	○	0	433MHz	Dias	●	●
MAXUS	G20	2019/04-2022/12	433MHz C00047579		●	●	○	0	433MHz	Dias	●	●
MAXUS	G20	2019/04-2022/12	433MHz		●	●	○	0	433MHz	Dias	●	●
MAXUS	T60	2017/01-2022/12	433MHz		●	●	○	0	433MHz	Dias	●	●
MAXUS	T60	2017/01-2022/12	433MHz C00047579		●	●	○	0	433MHz	Dias	●	●
MAXUS	T70	2017/01-2022/12	433MHz		●	●	○	0	433MHz	Dias	●	●
MAXUS	T70	2017/01-2022/12	433MHz C00047579		●	●	○	0	433MHz	Dias	●	●
MAXUS	V80	2015/01-2021/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
MAXUS	V90	2020/01-2022/12	433MHz C00047579		○	●	○	C	433MHz	Dias	●	●
MG	GS	2016/09-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
MG	MG3	2013/09-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
MG	MG6	2012/01-2019/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
MG	ZS	2017/01-2020/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Mahindra	Black Mhawk Pickup	2019/01-2021/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Mahindra	Genio	2014/01-2022/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Mahindra	Pick-Up Dual Cab	2014/06-2021/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Mahindra	Scorpio	2014/06-2020/12	433MHz	U202	○	●	○	A	433MHz	Schrader	●	●
Mahindra	XUV500	2013/01-2021/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Maserati	4200 GT/Coupe	2002/01-2007/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Maserati	Alfieri	2019/01-2019/12	433MHz	M165	○	●	○	A	433MHz	Schrader	●	●
Maserati	Coupe	2001/01-2007/12	433MHz	M138	○	●	○	C	433MHz	Huf/Beru	●	●
Maserati	Ghibli	2013/01-2022/12	433MHz	M156/ M157	●	●	○	O/A	433MHz	Schrader	●	●
Maserati	GranCabrio	2010/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Maserati	GranCabrio	2015/07-2017/12	SCH 433MHz	M147	●	●	○	O/A	433MHz	Schrader	●	●
Maserati	GranTurismo	2011/01-2016/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Maserati	GranTurismo	2010/09-2013/12	433MHz	M145	●	●	○	O/A	433MHz	Huf/Beru	●	●
Maserati	GranTurismo	2014/01-2022/01	433MHz	M145	●	●	○	O/A	433MHz	Schrader	●	●
Maserati	GranTurismo	2017/01-2021/12	433MHz	M156/ M157	○	●	○	A	433MHz	Schrader	●	●
Maserati	Levante	2015/04-2022/12	433MHz	WM	○	●	○	A	433MHz	Schrader	●	●
Maserati	Levante	2020/01-2021/12	433MHz	M161	○	●	○	C	433MHz	Continental	●	●
Maserati	Levante	2018/01-2020/12	433MHz	M156D	○	●	○	A	433MHz	Continental	●	●
Maserati	Levante	2016/01-2019/12	433MHz	M161	●	●	○	O/A	433MHz	Schrader	●	●
Maserati	MC20	2020/01-2021/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Maserati	Quattroporte	2013/01-2022/12	433MHz	M156	●	●	○	O/A	433MHz	Schrader	●	●
Maserati	Quattroporte	2011/01-2013/12	433MHz	M139	●	●	○	A	433MHz	Huf/Beru	●	●
Maserati	Quattroporte	2010/01-2010/12	433MHz	M139	●	●	○	O/A	433MHz	Huf/Beru	●	●
Maserati	Quattroporte	2003/04-2009/12	433MHz	M139	●	●	○	O/A	433MHz	Huf/Beru	●	●
Maybach	Landaulet	2015/01-2019/12	433MHz		●	●	○	O/S	433MHz	Schrader	●	●
Maybach	Landaulet	2008/10-2014/12	433MHz	Ma009-127	●	●	○	O/S	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Maybach	Maybach 57	2002/02-2013/12	433MHz	Ma007	●	●	○	O/S	433MHz	Huf/Beru	●	●
Maybach	Maybach 62	2002/02-2013/12	433MHz	Ma007	●	●	○	O/S	433MHz	Huf/Beru	●	●
Maybach	S Series	2015/01-2021/12	433MHz		●	●	○	O/S	433MHz	Schrader	●	●
Mazda	BT Pickup	2020/01-2021/12	315MHz		○	●	○	S	315MHz	Schrader	●	●
Mazda	BT Pickup	2011/05-2019/12	433MHz	J26E	○	●	○	S	433MHz	Schrader	●	●
Mazda	BT Pickup	2006/01-2011/12	315MHz		○	●	○	S	315MHz	Continental	●	●
Mazda	BT-50	2021/01-2021/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Mazda	CX-3	2021/01-2021/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-3	2015/01-2018/02	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-3	2018/03-2020/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-30	2020/01-2021/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-4	2016/01-2019/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Mazda	CX-5	2011/11-2022/12	433MHz	J53C/J72A	○	●	○	A	433MHz	Continental	●	●
Mazda	CX-5	2021/01-2022/12	315MHz BDGF37140		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-5	2017/01-2020/12	Direct 315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-5	2012/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-7	2011/01-2012/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	CX-7	2010/01-2010/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	CX-7	2006/01-2009/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	CX-8	2021/01-2021/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-8	2017/01-2020/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	CX-9	2007/01-2012/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	CX-9	2013/01-2015/12	433MHz	J50C	○	●	○	A	433MHz	Continental	●	●
Mazda	CX-9	2018/01-2020/12	315MHz	J50C	○	●	○	A	315MHz	Continental	●	●
Mazda	CX-9	2016/01-2017/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	CX-9	2020/01-2021/12	315MHz	TC	○	●	○	A	315MHz	Continental	●	●
Mazda	MX-5	2018/01-2020/12	315MHz	ND	●	●	○	A	315MHz	Continental	●	●
Mazda	MX-5	2021/01-2022/12	315MHz	ND	○	●	○	A	315MHz	Continental	●	●
Mazda	MX-5	2010/05-2018/12	Indirect	ND	○	○	○	A	N/A	N/A	Indirect	●
Mazda	MX-5	2010/03-2015/04	315MHz	NC/J04C/J12 A	●	●	○	A	315MHz	Continental	●	●
Mazda	MX-5	2006/01-2010/02	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 2	2021/01-2021/12	315MHz	DJ	○	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 2	2011/01-2014/05	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 2	2015/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 2	2019/01-2020/12	315MHz		○	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 2	2014/06-2019/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Mazda	Mazda 3	2019/01-2021/12	ALL new 315MHz	BP	○	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 3	2014/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 3	2010/01-2010/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 3	2011/01-2013/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 5	2011/01-2015/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 5	2016/01-2017/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 6	2011/01-2013/12	315MHz		●	●	○	A	315MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mazda	Mazda 6	2014/01-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mazda	Mazda 6	2017/01-2020/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 6	2021/01-2021/12	315MHz	GL	○	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 6	2009/01-2010/12	315MHz		●	●	○	A	315MHz	Continental	●	●
Mazda	Mazda 6	2008/01-2008/12	315MHz		●	●	○	A	315MHz	Continental	●	●
McLaren	500 Series	2015/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	600 Series	2014/03-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	600LT	2018/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	700 Series	2017/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Elva	2020/01-2021/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
McLaren	GT	2019/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	MP4-12C	2011/01-2014/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	P1	2013/01-2020/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Senna	2020/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Senna	2017/01-2019/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Speedtail	2019/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Sports Series	2015/01-2022/06	F11001648001 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
McLaren	Sports Series	2015/01-2020/06	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
McLaren	Super Series	2017/01-2022/12	F11001648001 433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
McLaren	Super Series	2011/03-2021/06	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Mercedes	A Class	2012/01-2014/03	433MHz	W176	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	A Class	2014/04-2018/05	433MHz	W176	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	A Class	2018/06-2022/06	433MHz	W177	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	AMG	2013/01-2018/06	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	AMG GT	2014/01-2022/06	433MHz	C190	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	B Class	2011/02-2022/12	433MHz A0009054104		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	B Class	2011/11-2019/01	433MHz	W246/W242	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	C Class	2014/09-2018/05	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	C Class	2018/06-2021/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	C Class	2021/06-2023/12	433MHz	206	○	●	○	A	433MHz	Schrader	●	●
Mercedes	C Class	2014/03-2018/05	433MHz	W205	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	C Class	2007/01-2014/08	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CL Class	2000/01-2007/12	OYGRDKS-RE 315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
Mercedes	CL Class	2010/01-2015/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CL Class	2006/10-2010/12	315MHz		●	●	○	O/A	315MHz	Continental	●	●
Mercedes	CLA Class	2019/05-2022/12	433MHz	C118	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	CLA Class	2014/06-2019/04	433MHz	C117	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CLA Class	2012/12-2014/05	433MHz	C117	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CLK Class	2002/01-2012/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CLK Class	2006/01-2011/12	315MHz		●	●	○	O/A	315MHz	Continental	●	●
Mercedes	CLS Class	2017/01-2022/12	433MHz	C257	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CLS Class	2018/01-2019/12	433MHz	C218	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	CLS Class	2009/07-2017/12	433MHz	W218	●	●	○	O/A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mercedes	CLS Class	2006/01-2011/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Mercedes	CLS Class	2004/09-2011/12	Continental 433MHz	W219	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	E Class	2016/01-2022/12	433MHz	W213/BR238	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	E Class	1999/01-2005/12	315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	E Class	2005/06-2011/10	433MHz	W211	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	E Class	2006/01-2010/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Mercedes	E Class	2014/06-2018/12	433MHz	W212	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	E Class	2009/07-2014/05	433MHz	W212/C207	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	EQC	2019/05-2022/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	G Class	2018/06-2022/12	433MHz	G463	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	G Class	2007/04-2018/05	433MHz	G463/461	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GL Class	2006/04-2009/09	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Mercedes	GL Class	2006/01-2010/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Mercedes	GL Class	2009/06-2012/12	433MHz	X164	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GL Class	2013/01-2019/06	433MHz	X166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLA Class	2020/02-2022/12	433MHz	H247	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLA Class	2013/12-2020/06	433MHz	X156	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLB Class	2019/01-2022/12	433MHz	X247	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLB Class	2019/01-2019/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLC Class	2016/09-2022/12	433MHz	C253	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLC Class	2015/01-2019/07	433MHz	X253	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLE Class	2015/04-2019/11	433MHz	X166/C292	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLE Class	2018/10-2022/12	433MHz	V167	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLE Class	2019/01-2019/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLK Class	2008/01-2015/09	433MHz	X204	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLS Class	2015/01-2019/06	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	GLS Class	2019/01-2019/12	HUF 433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GLS Class	2019/07-2022/12	433MHz	X167	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	GT	2014/01-2022/12	433MHz	GT	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	M Class	2005/01-2009/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Mercedes	M Class	2005/01-2011/05	433MHz	W164	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	M Class	2010/01-2014/12	433MHz	W166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	ML Class	2011/06-2019/12	433MHz	W166	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	Marco Polo	2014/01-2022/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	R Class	2010/01-2018/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	R Class	2006/01-2009/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Mercedes	S Class	2018/01-2020/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	S Class	2013/07-2020/12	433MHz	W222/C217	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	S Class	2009/06-2013/06	433MHz	W221	●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	S Class	1999/07-2005/09	433MHz	W220	●	●	○	0/A	433MHz	Huf/Beru	●	●
Mercedes	S Class	2000/01-2006/12	Huf 315MHz		●	●	○	0/A	315MHz	Huf/Beru	●	●
Mercedes	S Class	2005/10-2009/05	433MHz	W221	●	●	○	0/A	433MHz	Continental	●	●
Mercedes	S Class	2005/12-2013/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●
Mercedes	SL Class	2012/07-2019/12	433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Mercedes	SL Class	2005/05-2012/12	315MHz		●	●	○	0/A	315MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mercedes	SL Class	2005/05-2012/06	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Mercedes	SL Class	2000/01-2005/04	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	SL Class	2000/01-2005/04	315MHz		●	●	○	O/A	315MHz	Huf/Beru	●	●
Mercedes	SLC Class	2016/01-2020/06	433MHz	R172	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	SLK Class	2004/01-2021/12	433MHz	R171, R172	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	SLR Class	2008/01-2009/12	315MHz		●	●	○	O/A	315MHz	Continental	●	●
Mercedes	SLR Class	2000/01-2007/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	SLR Class	2008/01-2010/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Mercedes	SLR McLaren	2004/01-2011/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	SLR McLaren	2008/01-2009/12	315MHz		●	●	○	O/A	315MHz	Continental	●	●
Mercedes	SLS Class	2010/01-2019/06	433MHz	197	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	Sprinter	2007/01-2014/12	315MHz		●	●	○	O/A	315MHz	Continental	●	●
Mercedes	Sprinter	2006/06-2011/10	433MHz	W906	●	●	○	O/A	433MHz	Continental	●	●
Mercedes	Sprinter	2018/01-2022/12	HUF 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mercedes	Sprinter	2018/01-2020/12	SCH 433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	Sprinter	2010/01-2018/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	Sprinter Combi	2011/11-2018/09	433MHz	906	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	V Class	2014/01-2022/12	433MHz	W447	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	Valente	2015/01-2021/12	433MHz	VS20	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	Valente	2012/01-2014/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Mercedes	Viano	2003/07-2014/05	Continental 433MHz	W639	●	●	○	O/A	433MHz	Continental	●	●
Mercedes	Vito	2003/05-2014/06	433MHz	W639	●	●	○	O/A	433MHz	Continental	●	●
Mercedes	Vito	2014/07-2021/12	433MHz	W640	●	●	○	O/A	433MHz	Schrader	●	●
Mercedes	X Class	2017/01-2020/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Mini	3-5 Doors Hatch	2014/01-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Mini	Clubman	2013/11-2022/12	433MHz	F54	●	●	○	A	433MHz	Continental	●	●
Mini	Clubman	2008/01-2013/12	Indirect	R55	○	○	○	A	N/A	N/A	Indirect	●
Mini	Clubvan	2012/07-2015/12	433MHz	R55	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Convertible	2014/01-2016/12	433MHz	R57	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Convertible	2009/01-2013/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Convertible	2015/01-2021/12	433MHz	F57	●	●	○	A	433MHz	Continental	●	●
Mini	Cooper	2014/03-2021/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Mini	Cooper	2006/01-2006/09	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mini	Cooper	2010/01-2015/12	OYGTSSRE4D 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Countryman	2015/07-2022/12	433MHz	F60	●	●	○	A	433MHz	Continental	●	●
Mini	Countryman	2011/01-2018/12	433MHz	R60	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Countryman	2009/01-2014/06	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Coupe	2011/01-2013/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Coupe	2011/07-2018/06	433MHz	R58	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Electric	2020/04-2022/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Mini	Mini	2006/03-2022/12	433MHz	F55/F56	●	●	○	A	433MHz	Continental	●	●
Mini	Paceman	2014/07-2018/06	433MHz	R61	●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Paceman	2009/01-2014/06	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Roadster	2014/05-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Mini	Roadster	2011/12-2014/12	433MHz	R59	●	●	○	O/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Mini	Superleggera	2014/03-2019/12	433MHz		●	●	○	A	433MHz	Continental	●	●
Mitsubishi	ASX	2014/01-2021/12	433MHz	GA0	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	ASX	2013/04-2019/02	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Eclipse Cross	2017/01-2022/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Express	2020/01-2021/12	433MHz		○	●	○	C	433MHz	Orange	●	●
Mitsubishi	Lancer	2014/01-2022/12	433MHz	CY0	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Lancer	2006/12-2020/12	315MHz 4250B975		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Lancer Sportback	2014/01-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Mirage	2013/01-2022/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Mirage	2013/07-2021/12	315MHz 4250D585		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Mirage	2013/01-2021/12	433MHz	A00	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Outlander	2019/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mitsubishi	Outlander	2014/01-2022/12	433MHz	CWO/GFO	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Outlander	2006/12-2022/12	315MHz 4250B975		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Outlander PHEV	2019/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Mitsubishi	Pajero	2016/01-2019/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Pajero	2014/01-2015/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Pajero	2014/01-2022/12	433MHz	V80	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Pajero Sport	2014/03-2019/12	433MHz	V80	●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Pajero Sport	2016/01-2019/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Pajero Sport	2014/01-2015/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Mitsubishi	Triton	2014/03-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Mitsubishi	Triton	2015/01-2019/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	2500	2015/01-2019/12	433MHz	F80	●	●	○	0	433MHz	Schrader	●	●
Nissan	370Z	2009/01-2020/06	315MHz	Z34	●	●	○	0	315MHz	Pacific	●	●
Nissan	370Z	2013/07-2021/06	PAC 433MHz	RC53D(2)/Z34	●	●	○	0/A	433MHz	Pacific	●	●
Nissan	370Z	2014/03-2019/12	SCH 433MHz		●	●	○	0/A	433MHz	Schrader	●	●
Nissan	370Z	2018/01-2019/12	VDO 433MHz		●	●	○	0/A	433MHz	Continental	●	●
Nissan	Almera	2013/01-2021/12	433MHz	LB1A/G11/B10	●	●	○	0	433MHz	Continental	●	●
Nissan	Altima	2014/03-2019/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Altima	2012/05-2019/09	407003JA0B 433MHz	L33	●	●	○	0	433MHz	Continental	●	●
Nissan	Cube	2011/01-2019/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
Nissan	Elgrand	2010/01-2017/12	315MHz	E52	●	●	○	0	315MHz	Pacific	●	●
Nissan	GT-R	2007/01-2022/12	315MHz	R35	●	●	○	0	315MHz	Schrader	●	●
Nissan	GT-R	2016/01-2021/12	VDO 433MHz	D52E	●	●	○	0	433MHz	Continental	●	●
Nissan	GT-R	2014/03-2022/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Nissan	Juke	2020/01-2021/12	KR5TIS-09DL 433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Juke	2010/01-2020/12	Smart key 315MHz	F15	●	●	○	0	315MHz	Pacific	●	●
Nissan	Juke	2014/03-2019/12	407005ZH0A 433MHz		●	●	○	0	433MHz	Pacific	●	●
Nissan	Juke	2012/07-2015/07	315MHz		●	●	○	0	315MHz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Nissan	Juke	2010/01-2017/12	Standard key 315MHz	F15	●	●	○	0	315MHz	Schrader	●	●
Nissan	Leaf	2010/10-2019/12	433MHz	ZE0/B12G	●	●	○	0	433MHz	Pacific	●	●
Nissan	Leaf	2004/03-2010/10	433MHz	ZE0/B12G	●	●	○	0	433MHz	Pacific	●	●
Nissan	Leaf	2017/01-2022/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Micra	2010/03-2019/12	433MHz	B02A/K13	●	●	○	0	433MHz	Pacific	●	●
Nissan	Murano	2004/01-2014/09	433MHz	Z51/P42D	●	●	○	0	433MHz	Schrader	●	●
Nissan	Murano	2014/06-2021/06	433MHz	Z51/Z52/P42M	●	●	○	0	433MHz	Pacific	●	●
Nissan	Navara	2017/01-2022/12	433MHz	Y62	●	●	○	0	433MHz	Pacific	●	●
Nissan	Navara	2004/10-2016/12	433MHz	D22/D23/D40/H61B/H60A	●	●	○	0	433MHz	Schrader	●	●
Nissan	Note	2013/01-2020/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Pathfinder	2004/01-2006/12	315MHz	R51	●	●	○	0	315MHz	Schrader	●	●
Nissan	Pathfinder	2007/01-2013/12	315MHz	R51	●	●	○	0	315MHz	Schrader	●	●
Nissan	Pathfinder	2013/01-2015/05	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Pathfinder	2015/11-2020/12	433MHz	R52/P61B	●	●	○	0	433MHz	Continental	●	●
Nissan	Pathfinder	2019/01-2021/12	407009DJOA 433MHz		○	●	○	C	433MHz	Continental	●	●
Nissan	Patrol	2010/01-2020/06	315MHz	E52	●	●	○	0	315MHz	Pacific	●	●
Nissan	Patrol	2019/01-2021/12	433MHz	T62	●	●	○	0	433MHz	Pacific	●	●
Nissan	Patrol	2014/03-2020/12	433MHz	Y62	●	●	○	0	433MHz	Pacific	●	●
Nissan	Primera	2002/01-2007/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Nissan	Pulsar	2016/01-2018/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Pulsar	2014/01-2019/12	315MHz		●	●	○	0	315MHz	Continental	●	●
Nissan	Pulsar	2014/01-2019/12	433MHz	C13M/C13/B12L	●	●	○	0	433MHz	Continental	●	●
Nissan	Qashqai	2019/06-2021/12	433MHz	J10/J11/P32S	●	●	○	0/A	433MHz	Continental	●	●
Nissan	Qashqai	2019/06-2022/12	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Nissan	Qashqai	2018/06-2019/05	433MHz	J10/J11/P32S	●	●	○	0/A	433MHz	Continental	●	●
Nissan	Qashqai	2016/01-2019/05	433MHz		●	●	○	0/A	433MHz	Continental	●	●
Nissan	Qashqai	2014/01-2018/05	433MHz	J10/J11/P32S	●	●	○	0/A	433MHz	Continental	●	●
Nissan	Qashqai	2013/01-2013/12	433MHz	J10/J11/P32S	●	●	○	0/A	433MHz	Continental	●	●
Nissan	Sunny	2020/01-2021/12	433MHz		●	●	○	0	433MHz	Continental	●	●
Nissan	Titan	2017/01-2022/12	433MHz 40700EZ00A		●	●	○	0	433MHz	Pacific	●	●
Nissan	X-Trail	2016/09-2021/12	433MHz	T32	●	●	○	0	433MHz	Continental	●	●
Nissan	X-Trail	2013/01-2019/12	433MHz	T32/P32R	●	●	○	0	433MHz	Continental	●	●
Opel/Vauxhall	Vectra	2002/01-2012/10	433MHz	0e86/GM Z3200	○	●	○	A	433MHz	Schrader	●	●
Peugeot	1007	2004/01-2011/12	433MHz	A08/PF1	●	●	○	0	433MHz	Continental	●	●
Peugeot	107	2012/01-2014/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	108	2014/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	2008	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	207	2005/11-2013/09	433MHz	A7	●	●	○	0	433MHz	Continental	●	●
Peugeot	207	2013/10-2016/12	433MHz	A7	●	●	○	0	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Peugeot	208	2012/05-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	3008	2016/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	3008	2013/10-2021/12	433MHz	T84	●	●	○	0	433MHz	Schrader	●	●
Peugeot	3008	2008/11-2013/08	433MHz	T84	●	●	○	0	433MHz	Schrader	●	●
Peugeot	307	2007/03-2008/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Peugeot	307	2001/01-2007/02	433MHz		●	●	○	0	433MHz	Continental	●	●
Peugeot	308	2014/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Peugeot	308	2007/01-2021/12	433MHz	T7	●	●	○	0	433MHz	Schrader	●	●
Peugeot	4008	2014/01-2021/12	433MHz	J3	●	●	○	0/S	433MHz	Continental	●	●
Peugeot	407	2003/01-2012/12	433MHz	D2	●	●	○	0	433MHz	Continental	●	●
Peugeot	408	2012/01-2019/12	433MHz	T73	●	●	○	0	433MHz	Schrader	●	●
Peugeot	5008	2017/10-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	5008	2009/01-2019/12	433MHz	T87	●	●	○	0	433MHz	Schrader	●	●
Peugeot	508	2013/10-2022/12	433MHz	W2	●	●	○	0/A	433MHz	Schrader	●	●
Peugeot	508	2010/09-2014/09	Continental 433MHz	W2	●	●	○	0	433MHz	Continental	●	●
Peugeot	607	2004/10-2012/12	433MHz	Z8	●	●	○	0	433MHz	Continental	●	●
Peugeot	807	2004/10-2014/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Peugeot	807	2002/02-2005/12	433MHz	V2/8052	●	●	○	0	433MHz	Schrader	●	●
Peugeot	Boxer	2018/01-2021/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Peugeot	Expert	2016/10-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Peugeot	Expert	2006/01-2010/12	433MHz	G9	●	●	○	0	433MHz	Schrader	●	●
Peugeot	Expert	2014/06-2019/12	433MHz	G9	●	●	○	0	433MHz	Schrader	●	●
Peugeot	Partner	2014/06-2021/12	433MHz	B9	●	●	○	0	433MHz	Schrader	●	●
Peugeot	Partner	2016/03-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Peugeot	RCZ	2013/10-2019/12	433MHz	T75	●	●	○	0	433MHz	Schrader	●	●
Peugeot	RCZ	2009/01-2013/09	433MHz	T75	●	●	○	0	433MHz	Schrader	●	●
Porsche	718 (982)	2016/01-2021/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	911	2010/01-2016/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Porsche	911 (991)	2017/01-2020/12	433MHz	991	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	911 (991)	2011/01-2016/12	433MHz	991	●	●	○	A	433MHz	Huf/Beru	●	●
Porsche	911 (992)	2017/01-2022/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	911 (997)	2008/04-2015/08	433MHz	997	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	911 (997)	2004/01-2008/06	OYGTSSRE4B 433MHz	997	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	918 Spyder	2013/01-2015/12	433MHz		●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	960	2015/09-2019/06	433MHz	714	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Boxster	2004/01-2008/12	433MHz	987	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Boxster	2009/01-2013/12	433MHz	987	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Boxster	2012/01-2016/12	433MHz	981	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Carrera GT	2003/01-2011/12	433MHz	GT	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne	2017/09-2022/12	433MHz	9YA	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne	2002/01-2006/12	433MHz	9PA	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne	2006/12-2010/12	433MHz	9PA	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne	2011/01-2014/07	433MHz	92A	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne	2014/11-2017/08	433MHz	92A	●	●	○	0/A	433MHz	Huf/Beru	●	●
Porsche	Cayenne S	2010/01-2014/05	433MHz	4. 8L	●	●	○	0/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Porsche	Cayman	2016/10-2022/12	433MHz	982/982C/CT4-2	●	●	○	O/A	433MHz	Huf/Beru	●	●
Porsche	Cayman	2013/04-2016/12	433MHz	981	●	●	○	O/A	433MHz	Huf/Beru	●	●
Porsche	Macan	2014/01-2022/12	433MHz	P0416/95B	●	●	○	O/A	433MHz	Huf/Beru	●	●
Porsche	Mission E	2019/01-2020/12	433MHz		○	●	○	C	433MHz	Huf/Beru	●	●
Porsche	Panamera	2017/09-2022/12	433MHz	970/971	●	●	○	O/A	433MHz	Huf/Beru	●	●
Porsche	Panamera	2009/01-2014/02	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Porsche	Panamera	2013/09-2017/08	433MHz	970	●	●	○	O/A	433MHz	Huf/Beru	●	●
Porsche	Taycan	2019/01-2022/12	433MHz 9J1907275		○	●	○	C	433MHz	Huf/Beru	●	●
Renault	Alaskan	2018/01-2019/12	433MHz	U60A	○	●	○	C	433MHz	Continental	●	●
Renault	Alaskan Pickup	2016/11-2021/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Renault	Alpine A110	2021/01-2021/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Renault	Captur	2013/01-2019/12	433MHz	J87	●	●	○	O	433MHz	Schrader	●	●
Renault	Clio III	2004/04-2014/05	433MHz	X85	●	●	●	O	433MHz	Schrader	●	●
Renault	Clio IV	2014/06-2019/12	433MHz	X85/X98	●	●	○	O	433MHz	Schrader	●	●
Renault	Clio IV	2016/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Renault	Fluence	2009/01-2021/06	433MHz	L38	●	●	○	O	433MHz	Continental	●	●
Renault	Fluence	2015/01-2019/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Renault	Kadjar	2015/01-2022/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Renault	Kangoo	2007/10-2021/06	433MHz	X61	●	●	○	C	433MHz	Schrader	●	●
Renault	Koleos	2013/01-2016/07	Y 433MHz		●	●	○	O	433MHz	Continental	●	●
Renault	Koleos	2008/02-2015/12	LCV 433MHz	H45	●	●	○	O	433MHz	Schrader	●	●
Renault	Koleos	2016/01-2019/12	LCV 433MHz	H45	●	●	○	O	433MHz	Schrader	●	●
Renault	Koleos	2017/01-2021/12	433MHz 407004CBOA		○	●	○	C	433MHz	Continental	●	●
Renault	Laguna II	2000/12-2010/03	433MHz	X74	●	●	●	O	433MHz	Schrader	●	●
Renault	Laguna III	2007/01-2016/12	433MHz	X91	●	●	○	O	433MHz	Continental	●	●
Renault	Latitude	2010/09-2015/12	433MHz	L43	●	●	○	O	433MHz	Continental	●	●
Renault	Latitude	2016/01-2019/12	433MHz	L43	●	●	○	O	433MHz	Continental	●	●
Renault	Master	2009/11-2022/12	433MHz	X62	●	●	○	O	433MHz	Schrader	●	●
Renault	Megane I	1997/01-2005/03	433MHz	B32/X95/X64	●	●	●	O	433MHz	Schrader	●	●
Renault	Megane II	2002/01-2009/12	433MHz	B32/X84	●	●	●	O	433MHz	Continental	●	●
Renault	Megane III	2008/10-2019/12	433MHz	X95	●	●	○	O	433MHz	Continental	●	●
Renault	Megane IV	2016/01-2022/12	RFB 433MHz		●	●	○	O/A	433MHz	Continental	●	●
Renault	Trafic	2014/01-2021/12	433MHz	X82	●	●	○	O	433MHz	Schrader	●	●
Renault	Zoe	2012/09-2019/06	433MHz	X10	●	●	○	O	433MHz	Continental	●	●
Renault	Zoe	2019/07-2022/12	433MHz		●	●	○	O	433MHz	Continental	●	●
Rolls Royce	Cullinan	2018/01-2021/12	433MHz	R31	○	●	○	A	433MHz	Schrader	●	●
Rolls Royce	Dawn	2016/01-2022/12	433MHz	RR6	○	●	○	C	433MHz	Huf/Beru	●	●
Rolls Royce	Drophead Coupe	2007/01-2018/12	433MHz	RR02	○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Ghost	2009/01-2010/12	433MHz 36236798726	RR04	○	●	○	C	433MHz	Huf/Beru	●	●
Rolls Royce	Ghost	2011/01-2019/12	433MHz	RR04	○	●	○	C	433MHz	Huf/Beru	●	●
Rolls Royce	Ghost	2020/01-2021/06	433MHz	RR21	○	●	○	C	433MHz	Huf/Beru	●	●
Rolls Royce	Phantom	2012/01-2017/12	433MHz	RR01	○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Phantom	2007/01-2022/12	OYGTSSRE4DB 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Rolls Royce	Phantom	2003/02-2017/12	OYGTSSRE4TC 433MHz	RR01	○	●	○	A	433MHz	Huf/Beru	●	●
Rolls Royce	Phantom	2017/01-2022/12	MRXAG5SP4 433MHz	RR11	○	●	○	A	433MHz	Schrader	●	●
Rolls Royce	Wraith	2013/01-2022/12	433MHz	RR5	○	●	○	C	433MHz	Huf/Beru	●	●
Saab	9-3	2003/01-2006/09	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
Saab	9-3	2006/10-2009/05	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
Saab	9-3	2009/06-2012/12	433MHz	YS3F	○	●	○	A	433MHz	Schrader	●	●
Saab	9-3	2013/01-2014/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Saab	9-3X	2007/07-2014/04	433MHz		○	●	○	A	433MHz	Schrader	●	●
Saab	9-4X	2011/01-2014/06	433MHz		●	●	●	O/A	433MHz	Schrader	●	●
Saab	9-5	2002/07-2006/10	433MHz	YE3E	○	●	○	A	433MHz	Schrader	●	●
Saab	9-5	2006/11-2009/09	433MHz	YE3E	○	●	○	A	433MHz	Schrader	●	●
Saab	9-5	2009/10-2012/12	433MHz	YS3G	●	●	●	O/A	433MHz	Schrader	●	●
Saab	9-7X	2007/01-2009/12	433MHz		○	●	○	S	433MHz	Schrader	●	●
Skoda	Fabia	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Fabia	2013/10-2014/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Fabia	2015/01-2021/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Karoq	2017/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Kodiaq	2016/11-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Kodiaq	2016/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Skoda	Octavia	2012/10-2014/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Octavia	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Octavia	2015/01-2021/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Skoda	Praktik	2013/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Rapid	2012/01-2015/04	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Rapid	2015/05-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Rapid	2017/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Rapid	2012/01-2016/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Roomster	2006/01-2018/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Roomster	2013/01-2020/06	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Scala	2019/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Superb	2015/05-2016/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Superb	2013/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Superb	2017/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Skoda	Superb	2008/03-2015/04	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Skoda	Yeti	2014/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Skoda	Yeti	2009/06-2018/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Smart	Forfour	2005/01-2021/12	433MHz	A453	●	●	○	O/A	433MHz	Schrader	●	●
Smart	Fortwo	2007/01-2019/12	433MHz	A451	●	●	○	O/A	433MHz	Schrader	●	●
Ssangyong	Actyon	2018/07-2019/12	Q200 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Actyon	2012/08-2021/12	QJ 433MHz		○	●	○	A	433MHz	Schrader	●	●
Ssangyong	Actyon Sport	2012/10-2018/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Ssangyong	Chairman	2014/01-2019/12	4199034000 433MHz		●	●	○	A	433MHz	Schrader	●	●
Ssangyong	Korando	2018/01-2022/12	C300 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Korando	2010/11-2022/12	C200 433MHz		○	●	○	A	433MHz	Schrader	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Ssangyong	Korando	2019/05-2022/06	4199037000 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	LUVi	2015/01-2019/12	X100 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Musso	2016/01-2018/05	433MHz		○	●	○	A	433MHz	Schrader	●	●
Ssangyong	Musso	2018/06-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Nomad	2013/07-2019/10	433MHz		○	●	○	A	433MHz	Schrader	●	●
Ssangyong	Rexton	2017/03-2022/12	Y400 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Rexton	2012/07-2017/12	Y300 433MHz		●	●	○	A	433MHz	Schrader	●	●
Ssangyong	Rodius	2005/05-2021/12	AJ 433MHz		○	●	○	A	433MHz	Schrader	●	●
Ssangyong	Stavic	2014/01-2018/12	433MHz		○	●	○	A	433MHz	Schrader	●	●
Ssangyong	Tivoli	2015/01-2020/06	X100 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Tivoli	2016/01-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Ssangyong	Turismo	2014/01-2022/12	AJ 433MHz		○	●	○	A	433MHz	Schrader	●	●
Subaru	BRZ	2011/11-2020/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
Subaru	BRZ	2014/01-2021/06	ZC 433MHz	ZC	●	●	○	0	433MHz	Pacific	●	●
Subaru	Forester	2018/01-2022/12	433MHz	FM5/PF3	●	●	○	0	433MHz	Schrader	●	●
Subaru	Forester	2014/01-2017/12	433MHz	FM5/PF3	●	●	○	0	433MHz	Schrader	●	●
Subaru	Impreza	2013/07-2022/12	315MHz		●	●	○	0	315MHz	Schrader	●	●
Subaru	Impreza	2016/09-2022/12	433MHz	HR3	●	●	○	0	433MHz	Schrader	●	●
Subaru	Impreza	2014/01-2016/12	433MHz	55A/MF1/ZR1	●	●	○	0	433MHz	Schrader	●	●
Subaru	Legacy	2014/01-2017/12	433MHz	EZ5	●	●	○	0	433MHz	Schrader	●	●
Subaru	Legacy	2018/01-2019/12	433MHz	EZ5	●	●	○	0	433MHz	Schrader	●	●
Subaru	Levorg	2015/01-2021/06	VM 433MHz		●	●	○	0	433MHz	Schrader	●	●
Subaru	Libery	2014/01-2017/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Subaru	Libery	2018/01-2020/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Subaru	Outback	2014/01-2017/12	433MHz	EZ5	●	●	○	0	433MHz	Schrader	●	●
Subaru	Outback	2018/01-2019/12	433MHz	EZ5	●	●	○	0	433MHz	Schrader	●	●
Subaru	Outback	2018/01-2022/12	433MHz	BS/BT	●	●	○	0	433MHz	Schrader	●	●
Subaru	Tribeca	2017/01-2020/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Subaru	WRX	2019/01-2021/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Subaru	WRX	2014/01-2018/12	XK 433MHz		●	●	○	0	433MHz	Schrader	●	●
Subaru	XV	2018/01-2021/12	433MHz	GT	●	●	○	A/O	433MHz	Schrader	●	●
Subaru	XV	2018/01-2019/12	433MHz	HR3	●	●	○	0	433MHz	Schrader	●	●
Subaru	XV	2012/01-2017/12	433MHz	MF1	●	●	○	0	433MHz	Schrader	●	●
Suzuki	APV	2014/06-2019/12	433MHz	YC5/YRA	○	●	○	C	433MHz	Continental	●	●
Suzuki	Baleno	2015/01-2022/12	433MHz	YR	●	●	○	0	433MHz	Continental	●	●
Suzuki	Celerio	2014/03-2022/12	433MHz	YLA	○	●	○	C	433MHz	Continental	●	●
Suzuki	Grand Vitara	2014/06-2021/06	433MHz	YT4	●	●	○	0	433MHz	Continental	●	●
Suzuki	Ignis	2016/01-2021/06	433MHz	YJ	●	●	○	0	433MHz	Continental	●	●
Suzuki	Jimny	2014/06-2018/10	433MHz	YR7	●	●	○	0	433MHz	Continental	●	●
Suzuki	Jimny	2018/11-2021/06	433MHz	YW5	●	●	○	0	433MHz	Continental	●	●
Suzuki	Kizashi	2010/06-2019/12	433MHz	YW1	○	●	○	C	433MHz	Continental	●	●
Suzuki	SX4	2013/01-2021/12	433MHz	YY1, YY3	●	●	○	0	433MHz	Continental	●	●
Suzuki	SX4 S-Cross	2013/01-2021/12	433MHz	YAA	●	●	○	0	433MHz	Continental	●	●
Suzuki	Splash	2013/09-2019/12	433MHz	YV1/YV4/ YV5	○	●	○	C	433MHz	Continental	●	●
Suzuki	Swift	2013/08-2021/06	433MHz	YP6/YP7/YS	●	●	○	0	433MHz	Continental	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Suzuki	Swift Sport	2016/01-2020/12	433MHz		○	●	○	C	433MHz	Continental	●	●
Suzuki	Vitara	2014/01-2021/06	433MHz	YFA/YG4/YH4	●	●	○	O	433MHz	Continental	●	●
Tata	Xenon XT	2016/01-2021/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Tesla	Model 3	2018/01-2021/12	433MHz (10748 1200B)		○	●	○	A	433MHz	Continental	●	●
Tesla	Model 3	2016/01-2020/08	433MHz		○	●	○	A	433MHz	Continental	●	●
Tesla	Model S	2012/01-2014/09	433MHz		○	●	○	A	433MHz	Baolong	●	●
Tesla	Model S	2014/09-2022/12	433MHz		○	●	○	A	433MHz	Continental	●	●
Tesla	Model X	2016/01-2019/12	Baolong 433MHz		○	●	○	A	433MHz	Baolong	●	●
Tesla	Model X	2014/10-2022/12	Continental 433MHz		○	●	○	A	433MHz	Continental	●	●
Tesla	Roadster	2008/01-2010/12	Huf 433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Tesla	Roadster	2010/01-2012/12	Baolong 433MHz		○	●	○	A	433MHz	Baolong	●	●
Toyota	86	2012/04-2022/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Aurion (H_Line)	2014/01-2020/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Aurion (L_Line)	2014/01-2020/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Avensis	2008/10-2019/12	C210 433MHz	312N/445L	●	●	○	O	433MHz	Pacific	●	●
Toyota	C-HR	2017/01-2019/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	C-HR	2016/01-2023/06	433MHz	560A	●	●	○	O/A	433MHz	Pacific	●	●
Toyota	Camry	2006/01-2011/09	Japan/USA 315MHz		●	●	○	O	315MHz	Pacific	●	●
Toyota	Camry	2014/01-2021/12	C210 433MHz	045L	●	●	○	O	433MHz	Pacific	●	●
Toyota	Camry	2016/01-2022/12	C215 433MHz	045L	●	●	○	O/A	433MHz	Pacific	●	●
Toyota	Camry Hybrid	2014/01-2017/09	433MHz	XV50/XV70	●	●	○	O	433MHz	Pacific	●	●
Toyota	Coaster	2008/01-2019/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Corolla	2013/01-2021/12	C210 433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Corolla	2019/01-2022/12	C215 433MHz	740A	●	●	○	O/A	433MHz	Pacific	●	●
Toyota	FJ Cruiser	2014/06-2022/12	433MHz	155L	●	●	○	O	433MHz	Pacific	●	●
Toyota	Fortuner	2005/12-2022/12	433MHz	669L	●	●	○	O	433MHz	Pacific	●	●
Toyota	GR Supra	2019/01-2022/12	433MHz		●	●	○	O	433MHz	Huf/Beru	●	●
Toyota	Granvia	2019/01-2022/12	433MHz		○	●	○	C	433MHz	Pacific	●	●
Toyota	Hiace	2004/08-2022/12	433MHz	550N	●	●	○	O	433MHz	Pacific	●	●
Toyota	Highlander	2013/01-2020/12	433MHz	397L	●	●	○	O	433MHz	Pacific	●	●
Toyota	Hilux	2009/01-2022/12	433MHz	669L/640A	●	●	○	O	433MHz	Pacific	●	●
Toyota	Kluger	2014/01-2020/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Kluger	2007/01-2011/12	315MHz		●	●	○	O	315MHz	Pacific	●	●
Toyota	Kluger	2020/01-2021/12	433MHz	XU70	●	●	○	O	433MHz	Pacific	●	●
Toyota	Land Cruiser	2015/10-2022/12	433MHz	215L/611L	●	●	○	O	433MHz	Pacific	●	●
Toyota	Land Cruiser	2005/01-2013/08	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Land Cruiser	2014/01-2021/12	433MHz		●	●	○	O	433MHz	Pacific	●	●
Toyota	Land Cruiser Prado	2009/01-2017/09	433MHz	611L	●	●	○	O	433MHz	Pacific	●	●
Toyota	Previa	2007/01-2020/12	433MHz	085X/085L	●	●	○	O	433MHz	Pacific	●	●
Toyota	Prius	2003/08-2012/12	315MHz		●	●	○	O	315MHz	Pacific	●	●
Toyota	Prius	2019/01-2022/12	433MHz		●	●	○	O	433MHz	Pacific	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Toyota	Prius	2014/01-2018/12	433MHz	590L/030A/XW30/XW50/690A/277N	●	●	○	0	433MHz	Pacific	●	●
Toyota	Prius C	2014/03-2022/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Toyota	RAV4	2012/01-2019/09	433MHz	410A/XA40/120L	●	●	○	0	433MHz	Pacific	●	●
Toyota	RAV4	2005/11-2013/12	433MHz	120L/XA30	●	●	○	0	433MHz	Pacific	●	●
Toyota	Rukus	2014/01-2019/12	315MHz		●	●	○	0	315MHz	Pacific	●	●
Toyota	Tarago	2014/01-2020/12	433MHz		●	●	○	0	433MHz	Pacific	●	●
Toyota	Urban Cruiser	2007/06-2020/12	433MHz	260L	●	●	○	0	433MHz	Pacific	●	●
Toyota	Yaris	2011/01-2022/12	C210 433MHz	020L/850L	●	●	○	0	433MHz	Pacific	●	●
Volkswagen	Amarok	2014/03-2022/12	433MHz		●	●	○	A	433MHz	Schrader	●	●
Volkswagen	Arteon	2017/01-2022/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	CC	2018/01-2022/12	MQB 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	CC	2011/06-2020/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Caddy	2014/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	California	2019/11-2022/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Volkswagen	Caravelle	2019/11-2022/12	433MHz		○	●	○	A	433MHz	Huf/Beru	●	●
Volkswagen	Caravelle	2015/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Crafter	2018/03-2022/12	433MHz		●	●	○	0	433MHz	Schrader	●	●
Volkswagen	Crafter	2014/07-2018/02	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Crafter	2006/04-2014/06	433MHz	VN830	●	●	○	O/A	433MHz	Schrader	●	●
Volkswagen	Crafter	2006/01-2016/12	433MHz Continental		○	●	○	C	433MHz	Continental	●	●
Volkswagen	EOS	2014/01-2015/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Golf	2012/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Golf	2009/01-2021/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Jetta	2013/01-2019/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Volkswagen	Multivan	2004/03-2015/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Multivan	2019/10-2022/12	433MHz		○	●	○	C	433MHz	Schrader	●	●
Volkswagen	Multivan	2015/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	New Beetle	2011/08-2020/06	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Volkswagen	Passat	2014/09-2022/12	433MHz	B8	●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Passat	2012/01-2021/12	Indirect		○	○	○	S	N/A	N/A	Indirect	●
Volkswagen	Passat	2010/01-2015/12	433MHz	B6/VW471	●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Passat	2005/01-2011/12	433MHz	VW451	●	●	○	O/A	433MHz	Continental	●	●
Volkswagen	Passat CC	2014/09-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Passat CC	2008/03-2016/12	3AA907275 433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Phaeton	2010/06-2019/12	433MHz	Vh67	●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Phaeton	2001/12-2007/05	433MHz	VW611	●	●	○	A	433MHz	Huf/Beru	●	●
Volkswagen	Polo	2009/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Polo	2017/09-2020/12	433MHz		●	●	○	A	433MHz	Huf/Beru	●	●
Volkswagen	Scirocco	2008/06-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Scirocco	2008/01-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	T-ROC	2017/11-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	T5	2014/03-2019/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Tiguan	2012/01-2018/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●

Make	Model	Year Range	Feature	Model code	OBD-II Function	Programming Status	TireType/ Pressure Selection	Relearn Type (A=Automatic, S=Stationary, O=OBD, C=Copy)	Frequency	Sensor Manufacturer	Support by Autel (MX-Sensor)	Support by Autel (Tool)
Volkswagen	Touareg	2002/02-2007/12	433MHz	7L	●	●	○	A	433MHz	Huf/Beru	●	●
Volkswagen	Touareg	2012/01-2014/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Touareg	2014/08-2022/12	433MHz	7P5/7P6108	●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Touareg	2007/01-2011/12	433MHz		●	●	○	O/A	433MHz	Huf/Beru	●	●
Volkswagen	Transporter	2014/03-2021/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Volkswagen	Transporter	2015/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volkswagen	Up!	2011/08-2018/12	433MHz	VW120	●	●	○	O/A	433MHz	Huf/Beru	●	●
Volvo	C30	2011/01-2014/03	433MHz	Y279	●	●	○	O/A	433MHz	Continental	●	●
Volvo	C30 Electric	2011/01-2013/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Volvo	C70	2006/01-2007/12	433MHz	V70064	●	●	○	O/A	433MHz	Continental	●	●
Volvo	C70	2011/01-2014/12	433MHz	V70064	●	●	○	O/A	433MHz	Continental	●	●
Volvo	C70	2008/01-2010/12	433MHz	V70064	●	●	○	O/A	433MHz	Continental	●	●
Volvo	S40	2011/01-2014/12	433MHz	V40044	●	●	○	O/A	433MHz	Continental	●	●
Volvo	S40	2003/01-2010/12	433MHz	V40044	●	●	○	O/A	433MHz	Continental	●	●
Volvo	S60	2013/02-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S60	2018/01-2021/06	433MHz	V431	●	●	○	O/A	433MHz	Schrader	●	●
Volvo	S60	2010/01-2017/12	433MHz	Y283/V634	●	●	○	A	433MHz	Continental	●	●
Volvo	S80	2013/01-2019/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	S80	2006/01-2013/02	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Volvo	S90	2016/01-2021/06	433MHz	V541	●	●	○	O/A	433MHz	Schrader	●	●
Volvo	V40	2015/01-2020/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V40	2012/01-2020/12	433MHz	Y555, Y556	●	●	○	O/A	433MHz	Continental	●	●
Volvo	V50	2016/01-2018/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V50	2011/01-2016/12	433MHz	V5004-124	●	●	○	O/A	433MHz	Continental	●	●
Volvo	V50	2003/01-2010/12	433MHz	V5004-124	●	●	○	O/A	433MHz	Continental	●	●
Volvo	V60	2012/01-2022/12	433MHz 31341893		●	●	○	O/A	433MHz	Continental	●	●
Volvo	V60	2015/09-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V60	2017/11-2022/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Volvo	V60	2008/01-2014/06	433MHz	Y352	●	●	○	O/A	433MHz	Continental	●	●
Volvo	V60 Cross Country Wagon	2015/01-2018/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Volvo	V70	2007/01-2016/12	433MHz	Y285	●	●	○	O/A	433MHz	Continental	●	●
Volvo	V90	2016/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	V90	2015/01-2022/12	433MHz	V542	●	●	○	O/A	433MHz	Schrader	●	●
Volvo	XC40	2017/01-2022/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC40	2018/01-2019/12	433MHz		●	●	○	O/A	433MHz	Schrader	●	●
Volvo	XC60	2017/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC60	2015/01-2022/12	433MHz	Y413	●	●	○	O/A	433MHz	Continental	●	●
Volvo	XC70	2014/07-2018/12	433MHz		●	●	○	O/A	433MHz	Continental	●	●
Volvo	XC70	2010/01-2014/06	433MHz	Y381	●	●	○	O/A	433MHz	Continental	●	●
Volvo	XC70	2008/01-2009/12	433MHz	Y381	●	●	○	O/A	433MHz	Continental	●	●
Volvo	XC90	2015/01-2022/12	433MHz	V526	●	●	○	O/A	433MHz	Schrader	●	●
Volvo	XC90	2016/01-2021/12	Indirect		○	○	○	A	N/A	N/A	Indirect	●
Volvo	XC90	2002/01-2018/05	433MHz	Y289	●	●	○	O/A	433MHz	Schrader	●	●